

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

OCT 17 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1629540737

OPERATOR

Initial Report Final Report

Name of Company: Occidental Permian LTD <i>157984</i>	Contact: John Erickson
Address: N/A	Telephone No. : (505) 397-8236
Facility Name: OXY Benelli #1	Facility Type: Tank Battery
Surface Owner: Federal	Mineral Owner: Federal
API No.: 30-015-34811 <i>34881</i>	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	8	25S	28E	990	North	660	West	Lea <i>EDDY</i>

Latitude 32°08'57.16" Longitude: -104°06'59.44"

NATURE OF RELEASE

Type of Release: Surface <i>* CRUDE</i>	Volume of Release: 10 bbl.	Volume Recovered: 10 bbl.
Source of Release: Overfilled tanker trailer	Date and Hour of Occurrence: 10/01/16 at 1700	Date and Hour of Discovery: 10/01/16 at 1700
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* ***
The driver overfilled his tanker trailer releasing approximately 10 bbl. of crude onto the caliche pad. Caliche was applied to the pad to absorb the pooled crude, and the spill area was excavated using a backhoe.

Describe Area Affected and Cleanup Action Taken.*
A backhoe was used to excavate the impacted caliche pad. Two confirmation soil samples were collected for the excavated area, and one background soil sample was collected on October 2, 2016 and submitted for laboratory analyses. Laboratory analytical results indicated elevated chemicals of concern in confirmation soil sample 1@9". Therefore, on October 12, 2016, additional excavation was performed. An additional confirmation soil sample was collected from the excavated area and submitted for laboratory analyses. Analytical results for the soil sample collected on October 12, 2016 are pending. The laboratory analytical results for the soil samples collected on October 2, 2016 are attached. The excavated soil is stockpiled on site pending disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: Christopher R. Haugstad	Signed By <i>[Signature]</i>	Approved by Environmental Specialist:
Title: Senior Geologist	Approval Date: <i>10/16/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: chaugstad@broadbentinc.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: October 17, 2016 Phone: (830) 816-5434	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 11/26/16 *22P-344*

Bratcher, Mike, EMNRD

From: Laurel Galm <Lgalm@broadbentinc.com>
Sent: Monday, October 17, 2016 4:07 PM
To: Bratcher, Mike, EMNRD
Subject: Initial C-141 Report - OXY Benelli #1 Tank Battery, Carlsbad, NM
Attachments: Initial C-141 Report - OXY Benelli #1 Carlsbad, NM.PDF

Mr. Bratcher,

Per our conversation last week, I've attached the Initial C-141 Report for the crude spill that occurred at the OXY Benelli #1 Tank Battery in Carlsbad, NM. The final report will follow once we receive final lab results and waste disposal documentation. Please let me know if you have any questions.

Thank you,

Laurel Galm, GIT, CAPM
Project Geologist

113 Falls Court, Suite 700, Boerne, TX 78006
[T] 830-816-5434 • [F] 830-816-5436 • [C] 210-289-0924
lgalm@broadbentinc.com



CONFIDENTIALITY: This communication, including attachments, is for the exclusive use of the addressee(s) and may contain proprietary, confidential or privileged information. If you are not the intended recipient, any use, copying, disclosure, or distribution or the taking of any action in reliance upon this information is strictly prohibited. If you are not the intended recipient, please notify the sender immediately and delete this communication and destroy all copies.