

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB163053944

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: FIREFOX 4 FEDERAL COM #005H	Facility Type: Battery
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-41423	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	4	19S	31E	670	South	250	West	Eddy

Latitude 32.684082 Longitude -103.8822098

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 16 bbls PW	Volume Recovered: 15 bbls PW
Source of Release: Water Line	Date and Hour of Occurrence: 10/15/2016 unknown	Date and Hour of Discovery: 10/15/2016 8:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a cracked 4" Tee on the water line running to the water tank. The cracked fitting was replaced with a new fitting. Vacuum trucks were immediately dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

The release remained within the lined facility. All free standing fluid has been removed and the contaminated gravel has been replaced with fresh gravel. Concho will have the spill site inspected for any possible contamination from the release and will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dakota Neel</i>	OIL CONSERVATION DIVISION	
Printed Name: Dakota Neel	Approved by Environmental Specialist:	
Title: Environmental Coordinator	Approval Date:	Expiration Date:
E-mail Address: dneel2@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: October 24, 2016	Phone: 575-748-6933	

* Attach Additional Sheets If Necessary

2RP-3963