

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1163D550256

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: FOLK FEDERAL TANK BATTERY	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-013-20198
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	17	17S	29E					Eddy

Latitude 32.836062 Longitude -104.090789

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 18 bbls of Oil	Volume Recovered: 16 bbls of Oil
Source of Release: Hole in Tank	Date and Hour of Occurrence: 10/14/2016 unknown	Date and Hour of Discovery: 10/14/2016 12:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a hole in the bottom of the oil tank. The tank was taken out of service and the valves going to it were closed. Vacuum trucks were immediately dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred and remained within the bermed area of the facility. The contaminated gravel has been removed and replaced with fresh gravel. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Dakota Neel</i>	Approved by Environmental Specialist:	
Printed Name: Dakota Neel	Approval Date:	Expiration Date:
Title: Environmental Coordinator	Conditions of Approval:	
E-mail Address: dneel2@concho.com	Attached <input type="checkbox"/>	
Date: October 24, 2016 Phone: 575-748-6933		

* Attach Additional Sheets If Necessary

2RP-3964