

Report Date: June 8, 2009
SCB 23 #7 Spill

Work Order: 9060841
Spill @ 8"-10" Composites

Page Number: 1 of 2

Summary Report

Cheryl Winkler
Range Operating-Eunice

Report Date: June 8, 2009

P. O. Box 1570
Eunice, NM 88231

Work Order: 9060841



Project Name: Spill @ 8"-10" Composites
Project Number: SCB 23 #7 Spill

Sample	Description	Matrix	Date Taken	Time Taken	Date Received
198218	Spill @ 8"-10" N End	soil	2009-06-03	14:00	2009-06-08
198219	Spill @ 8"-10" S End	soil	2009-06-03	14:10	2009-06-08
198220	Middle Area	soil	2009-06-03	14:25	2009-06-08
198221	Background	soil	2009-06-03	13:30	2009-06-08

Sample: 198218 - Spill @ 8"-10" N End

Param	Flag	Result	Units	RL
Chloride		23400	mg/Kg	3.25

Sample: 198219 - Spill @ 8"-10" S End

Param	Flag	Result	Units	RL
Chloride		12500	mg/Kg	3.25

Sample: 198220 - Middle Area

Param	Flag	Result	Units	RL
Chloride		46300	mg/Kg	3.25

Sample: 198221 - Background

Report Date: June 8, 2009
SCB 23 #7 Spill

Work Order: 9060841
Spill @ 8"-10" Composites

Page Number: 2 of 2

Param	Flag	Result	Units	RL
Chloride		45.5	mg/Kg	3.25
