

Bratcher, Mike, EMNRD

From: Cheryl [cmwink@mac.com]
Sent: Thursday, June 18, 2009 10:29 AM
To: Bratcher, Mike, EMNRD
Subject: Fwd: SCB #4 Spill Area (9061509)
Attachments: Summary_Report.pdf; ATT5999487.htm

Mike, this is the cover on the SCB 23 No. 4 which matches the other caliche samples.

Cheryl

Begin forwarded message:

From: reports@traceanalysis.com
Date: June 16, 2009 1:54:08 PM MDT (CA)
To: cmwink@mac.com
Subject: SCB #4 Spill Area (9061509)

NOTE: To ensure you receive email, please add reports@traceanalysis.com to your address book.

TraceAnalysis, Inc.

(attachments enclosed)

Work Order: 9061509
Contact Person: Chris Garcia

Project Location: Remediation
Project Name: SCB #4 Spill
Project Number: SCB #4 Spill Area

Summary Report

Chris Garcia
Range Operating-Eunice

Report Date: June 16, 2009

P. O. Box 1570
Eunice, NM 88231

Work Order: 9061509



Project Location: Remediation
Project Name: SCB #4 Spill
Project Number: SCB #4 Spill Area

Sample	Description	Matrix	Date Taken	Time Taken	Date Received
198851	Comp. Backfill Area	soil	2009-06-13	15:55	2009-06-15

Sample - Field Code	BTEX				MTBE	TPH DRO	TPH GRO
	Benzene (mg/Kg)	Toluene (mg/Kg)	Ethylbenzene (mg/Kg)	Xylene (mg/Kg)	MTBE (mg/Kg)	DRO (mg/Kg)	GRO (mg/Kg)
198851 - Comp. Backfill Area	<0.0200	<0.0200	<0.0200	<0.0200		<50.0	<2.00

Sample: 198851 - Comp. Backfill Area

Param	Flag	Result	Units	RL
Chloride		2690	mg/Kg	3.25