

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

NOV 17 2016

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB114321051085

OPERATOR

Initial Report Final Report

Name of Company: Chevron USA Inc. 4323	Contact: Josepha DeLeon
Address: 6301 Deauville Blvd., Midland, TX 79706	Telephone No.: 575-263-0424
Facility Name: Skeen 34 1H	Facility Type: Oil Well
Surface Owner: Federal	Mineral Owner
API No.: 30-015-37805	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	34	26S	28E	165	South	2270	West	Eddy

Latitude: 32.00086889 Longitude: -103.0721928

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 23.15 Barrels of Water	Volume Recovered: 23.15 Barrels of Water
Source of Release: Heater Treater	Date and Hour of Occurrence: 11/08/2016 05:00 AM	Date and Hour of Discovery: 11/08/2016 05:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson - NMOCD Jim Amos - BLM	
By Whom? Josepha DeLeon	Date and Hour: 11/09/2016 07:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Heater treater water leak. All fluid was recovered.		
Describe Area Affected and Cleanup Action Taken.* Fluid leaked into lined secondary containment. Vacuum truck picked all fluid.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature:	Approved by Environmental Specialist:	
Printed Name: Josepha DeLeon	Approval Date: 11/21/16	Expiration Date: NA
Title: HES Specialist - Compliance Support, Environmental	Conditions of Approval:	
E-mail Address: jdx@chevron.com	Attached <input checked="" type="checkbox"/>	
Date: 11/17/2016	Phone: 575-263-0424	

* Attach Additional Sheets If Necessary

DRP-4004

Patterson, Heather, EMNRD

From: DeLeon, Josepha <JDXD@chevron.com>
Sent: Thursday, November 17, 2016 3:06 PM
To: Patterson, Heather, EMNRD; jamos@blm.gov
Cc: Barakat, Eli; Davis, Allen; Debeyssey, Svetlana
Subject: C-141 - Spill Skeen 34 1H
Attachments: Skeen 34 1H Spill C-141.pdf

Attached is the C-141 for the spill that occurred at the Skeen 34-1H.

If you need further information do not hesitate to contact me.

Josie DeLeon, HES Specialist -

Compliance Support - Environmental

Chevron - MCBU

(SE NM Areas, Dollarhide, Eunice, Hobbs and Vacuum)

1616 W. Bender Blvd.

Hobbs, NM 88240

575-263-0424

432-425-1528 - cell

idxd@chevron.com

<https://www.chevroncontractorsafety.com/contractormcbu/> - CHESM Contractor Website



Green/Red – The Doing Thinker