

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
Alameda District
Nov 24, 2016
RECEIVED
Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1633632758

OPERATOR

Initial Report Final Report

Name of Company Matador Production Company <i>228937</i>	Contact Catherine Green
Address 500 N Main St Ste 1 Roswell NM 88201	Telephone No. 575-627-2453
Facility Name Paul 25 24S 28E RB #221H	Facility Type Oil

Surface Owner Private	Mineral Owner Fee	API No. 30-015-43018
-----------------------	-------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	25	24S	28E	359	N	217	W	Eddy

Latitude 32.19484171 Longitude -104.0487226

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release ~560 bbls	Volume Recovered 240 bbls
Source of Release Line Split	Date and Hour of Occurrence Nov. 22, 2016 11am	Date and Hour of Discovery Nov. 22, 2016 10:30am
Was Immediate Notice Given? Required <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? Telephoned Mike Bratcher and Randy Bayliss. Left voicemails.	
By Whom? Catherine Green	Date and Hour Nov. 22, 2016 3pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*
Lease Operator observed 0 pressure on water line. Investigated by walking the line. Discovered severed pipe. Shut off well. Called for vacuum trucks. Line will be replaced.

Describe Area Affected and Cleanup Action Taken.*
See picture attached. Soil samples will be collected. Contaminated soil will be remediated/removed/replaced. Line will be fixed/replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Catherine Green</i>	OIL CONSERVATION DIVISION	
Printed Name: Catherine Green	Approved by Environmental Specialist: <i>Catherine Green</i>	
Title: Regulatory Analyst	Approval Date: <i>11/23/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: cgreen@matadorresources.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: Nov. 22, 2016	Phone: 575-627-2453	

2RP-4008





* Attach Additional Sheets If Necessary