

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NOV 29 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB 1433454353

OPERATOR

Initial Report Final Report

Name of Company <i>Devon Energy Production Company 10137</i>		Contact <i>Jake Harrington, Production Foreman</i>
Address <i>6488 Seven Rivers Hwy Artesia, NM 88210</i>		Telephone No. <i>432-214-5175</i>
Facility Name <i>Cotton Draw Unit SWD 181</i>		Facility Type <i>Salt Water Disposal</i>
Surface Owner State	Mineral Owner State	API No <i>30-015-41649</i>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	36	24S	31E	1568	North	1189	East	Eddy

Latitude: 32.1767349

Longitude: -103.7268524

NATURE OF RELEASE

Type of Release <i>Produced Water</i>	Volume of Release <i>80bbls</i>	Volume Recovered <i>80bbls</i>
Source of Release <i>Temporary frac tank</i>	Date and Hour of Occurrence <i>November 28, 2016 @ 8:30 AM</i>	Date and Hour of Discovery <i>November 28, 2016 @ 8:30 AM</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Shelly Tucker, BLM Mike Bratcher, OCD</i>	
By Whom? <i>Ray Carter, Asst. Production Foreman</i>	Date and Hour <i>Shelly Tucker, BLM November 28, 2016 @ 2:30 PM Mike Bratcher, OCD November 28, 2016 @ 2:40 PM</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse <i>N/A</i>	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Contract flowback personnel were transferring water from a minion tank to a frac tank when the frac tank started overflowing into lined containment. The valve to the frac tank was closed to stop further release.

Describe Area Affected and Cleanup Action Taken.*
Approximately 80bbls produced water was released into lined containment. A vacuum truck was contacted and recovered all 80bbls from lined containment. The lined containment was checked for holes and none were found. No further action is necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Sheila Fisher</i>	Signed By: <i>Mike Bratcher</i> Approved by Environmental Specialist.	
Title: Field Admin Support	Approval Date: <i>11/29/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>Sheila.fisher@dvn.com</i>	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: <i>11/29/16</i> Phone: <i>575.748.1829</i>		

* Attach Additional Sheets If Necessary

2RP-4016

Bratcher, Mike, EMNRD

From: Fisher, Sheila <Sheila.Fisher@dvn.com>
Sent: Tuesday, November 29, 2016 1:51 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Amber Groves (agroves@slo.state.nm.us)
Cc: Fulks, Brett; Harrington, Jake; Carter, Ray; McMahan, Mike
Subject: Cotton Draw Unit SWD 181_80bbls pw_11.28.16
Attachments: Cotton Draw Unit SWD 181_80bbls pw_Initial & Final C-141_11.28.16.doc; Cotton Draw Unit SWD 181_80bbls pw_GIS Image_11.28.16.pdf

Good Afternoon,

Attached please find the Initial & Final C-141 and GIS Image for the 80bbl produced water release at the Cotton Draw Unit SWD 181 on 11.28.16.

If you have any questions please feel free to contact me.

Thank you,

Sheila Fisher
Field Admin Support
Production
B-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.