

**NM OIL CONSERVATION**

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

DEC 13 2016

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.  
**RECEIVED**

**Release Notification and Corrective Action**

*NAB 1634951483*

Name of Company: <b>COG Operating LLC</b> <i>229137</i>		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address: <b>600 West Illinois Avenue, Midland TX 79701</b>		Contact:	<b>Robert McNeill</b>		
Facility Name: <b>MYOX 31 STATE COM #013H</b>		Telephone No.	<b>432-683-7443</b>		
		Facility Type:	<b>Tank Battery</b>		
Surface Owner:	State	Mineral Owner:	API No.	<b>30-015-37497</b>	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	31	25S	28E	660'	South	330'	East	Eddy

Latitude 32.0807419 Longitude 104.119072

**NATURE OF RELEASE**

Type of Release: <b>Oil</b>	Volume of Release: <b>30bbbls</b>	Volume Recovered: <b>28bbbls</b>
Source of Release: <b>Valve</b>	Date and Hour of Occurrence: <b>12-11-2016 11:15 am</b>	Date and Hour of Discovery: <b>12-11-2016 11:15 am</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Mike Bratcher - NMOCD / Amber Groves - SLO</b>	
By Whom? <b>Robert Grubbs Jr.</b>	Date and Hour: <b>Mon 12/12/2016 10:55 AM</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* <b>The release was caused by a corroded valve on the water tank. Replaced the valve with a new valve.</b>		
Describe Area Affected and Cleanup Action Taken.* <b>This release occurred within a lined facility. Vacuum trucks were dispatched to remove all freestanding fluids. Concho will have the spill area evaluated for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.</b>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>[Signature]</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Robert Grubbs Jr.</b>	Signed By: <i>[Signature]</i>	
Title: <b>Senior HSE Coordinator</b>	Approved by Environmental Specialist:	
E-mail Address: <b>rgrubbs@concho.com</b>	Approval Date: <b>12/13/16</b>	Expiration Date: <b>N/A</b>
Date: <b>December 13, 2016</b>	Phone: <b>432-683-7443</b>	Conditions of Approval:
		Attached <input checked="" type="checkbox"/>

\* Attach Additional Sheets If Necessary

*2RP-4033*

## Bratcher, Mike, EMNRD

---

**From:** Robert Grubbs <RGrubbs@concho.com>  
**Sent:** Tuesday, December 13, 2016 9:09 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; 'agroves@slo.state.nm.us'  
**Subject:** (C-141 Initial) MYOX 31 STATE COM #013H (TB) 30-015-37497  
**Attachments:** Myox 31 State Com #013H (TB) Initial.pdf

MR. BRATCHER / MS. GROVES,

ATTACHED IS A C-141 FOR YOUR CONSIDERATION. IF YOU HAVE ANY ADDITIONAL QUESTIONS PLEASE FEEL FREE TO CONTACT ME.

THANK YOU,

ROBERT GRUBBS JR.  
SR. HSE COORDINATOR  
432.683.7443 (MAIN)  
432.818.2369 (DIRECT)  
432.661.6601 (CELL)  
432.221.0892 (FAX)  
RGRUBBS@CONCHO.COM  
MAILING ADDRESS:  
ONE CONCHO CENTER  
600 W. ILLINOIS AVENUE  
MIDLAND, TEXAS 79701

CONFIDENTIALITY NOTICE: THE INFORMATION IN THIS EMAIL MAY BE CONFIDENTIAL AND/OR PRIVILEGED. IF YOU ARE NOT THE INTENDED RECIPIENT OR AN AUTHORIZED REPRESENTATIVE OF THE INTENDED RECIPIENT, YOU ARE HEREBY NOTIFIED THAT ANY REVIEW, DISSEMINATION OR COPYING OF THIS EMAIL AND ITS ATTACHMENTS, IF ANY, OR THE INFORMATION HEREIN, IS PROHIBITED. IF YOU RECEIVED THIS EMAIL IN ERROR, PLEASE IMMEDIATELY NOTIFY THE SENDER BY RETURN EMAIL AND DELETE THIS EMAIL FROM YOUR SYSTEM. THANK YOU.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

**Patterson, Heather, EMNRD**

---

**From:** Robert Grubbs <RGrubbs@concho.com>  
**Sent:** Monday, December 12, 2016 9:55 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; 'agroves@slo.state.nm.us'  
**Subject:** (Notification) MYOX 31 STATE COM #013H (TB) 30-015-37497

MR. BRATCHER / MS. GROVES,

COG OPERATING LLC IS REPORTING A RELEASE ON THE MYOX 31 STATE COM #013H (30-015-37497)

UNIT P SECTION 31 TOWNSHIP 25S RANGE 28E

THE RELEASE OCCURRED AT APPROXIMATELY 11:15 AM ON 12-11-2016

ESTIMATED RELEASED: APPROX. 30BBLS OIL

ESTIMATED RECOVERED: APPROX. 28BBLS OIL

THE RELEASE WAS CAUSED BY A CORRODED VALVE ON THE WATER TANK. THIS SPILL WAS CONTAINED WITHIN A LINED FACILITY. THIS AREA IS BEING EVALUATED AND A C-141 WILL BE SUBMITTED. IF YOU HAVE ANY ADDITIONAL QUESTIONS

THANK YOU,

ROBERT GRUBBS JR.  
SR. HSE COORDINATOR  
432.683.7443 (MAIN)  
432.818.2369 (DIRECT)  
432.661.6601 (CELL)  
432.221.0892 (FAX)  
RGRUBBS@CONCHO.COM  
MAILING ADDRESS:  
ONE CONCHO CENTER  
600 W. ILLINOIS AVENUE  
MIDLAND, TEXAS 79701

**CONFIDENTIALITY NOTICE:** THE INFORMATION IN THIS EMAIL MAY BE CONFIDENTIAL AND/OR PRIVILEGED. IF YOU ARE NOT THE INTENDED RECIPIENT OR AN AUTHORIZED REPRESENTATIVE OF THE INTENDED RECIPIENT, YOU ARE HEREBY NOTIFIED THAT ANY REVIEW, DISSEMINATION OR COPYING OF THIS EMAIL AND ITS ATTACHMENTS, IF ANY, OR THE INFORMATION HEREIN, IS PROHIBITED. IF YOU RECEIVED THIS EMAIL IN ERROR, PLEASE IMMEDIATELY NOTIFY THE SENDER BY RETURN EMAIL AND DELETE THIS EMAIL FROM YOUR SYSTEM. THANK YOU.

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.