

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**NM OIL CONSERVATION**  
ARTESIA DISTRICT  
State of New Mexico  
Energy Minerals and Natural Resources  
OCT 27 2016  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.  
**RECEIVED**

**Release Notification and Corrective Action**

**OPERATOR**       Initial Report       Final Report

Name of Company <b>LINN Energy</b>	Contact <b>EL GONZALES</b>
Address <b>2130 W BENDER HOBBS NM 88240</b>	Telephone No. <b>575-738-1739</b>
Facility Name <b>TURNER B 118</b>	Facility Type <b>OIL WELL E-FILE #710</b>

Surface Owner <b>BLM</b>	Mineral Owner <b>BLM</b>	API No. <b>30-015-28920</b> LEASE NO <b>LC-029395B</b>
--------------------------	--------------------------	---

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>M</b>	<b>20</b>	<b>17S</b>	<b>31E</b>					<b>EDDY</b>

Latitude **32.8156** Longitude **-103.9009**

**NATURE OF RELEASE**



Type of Release <b>PRODUCED WATER / HYDROCARBONS</b>	Volume of Release <b>UNKNOWN</b>	Volume Recovered <b>UNKNOWN</b>
Source of Release <b>WELL HEAD / STUFFING BOX</b>	Date and Hour of Occurrence	Date and Hour of Discovery <b>FEB 11</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken  
A release from the well head/stuffing box caused a release of fluid to leave the location and enter the pasture on the south side of the location and onto the lease road to the south/southwest of the location. The affected area is approximately 3' x 150' in each the pasture and the lease road. The affected area shows signs that remedial action had been taken, but not completed, the affected areas will be remediated and a work plan submitted to NM OCD and BLM for review and approval

Describe Area Affected and Cleanup Action Taken.\*  
Delineation complete

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>E. L. Gonzales</b>	Approved by Environmental Specialist: 	
Title: <b>Production Supervisor</b>	Approval Date: <b>12/22/16</b>	Expiration Date: <b>N/A</b>
E-mail Address: <b>ELgonzales.linnenergy.com</b>	Conditions of Approval: <b>Final</b>	Attached <input type="checkbox"/>
Date <b>9-7-16</b> Phone: <b>505-504-8002</b>		

\* Attach Additional Sheets If Necessary

**22P-710**