

Bratcher, Mike, EMNRD

From: Vernon Black [vernon@hungry-horse.com]
Sent: Wednesday, June 22, 2011 4:50 PM
To: Bratcher, Mike, EMNRD
Subject: RE: Closure Request Turner B #118

The depths varied a little bit as we were trying to remove as little as possible. The average depth is about 4'-5' except for the "Hole" on the west side of the road. We had to remove about 10' where the water had pooled.

I'll try to do better next time.....thanks of the help and the patience.

VKB

From: Bratcher, Mike, EMNRD [<mailto:mike.bratcher@state.nm.us>]
Sent: Wednesday, June 22, 2011 4:41 PM
To: tgregsto@blm.gov; Vernon Black
Cc: dpotter@linnenergy.com; Terry_gregston@nm.blm.gov
Subject: RE: Closure Request Turner B #118

Vernon,

Thanks for sending the diagram. I still do not know the depths the samples were taken, but assuming Terry is more familiar with this site than I am, and to keep things moving, I will say you are good to proceed.

MIKE BRATCHER

NMOCD District 2
1301 W. Grand Ave.
Artesia, NM 88210
575-748-1283 Ext.108
575-626-0857
mike.bratcher@state.nm.us

From: tgregsto@blm.gov [<mailto:tgregsto@blm.gov>]
Sent: Wednesday, June 22, 2011 11:43 AM
To: Vernon Black
Cc: dpotter@linnenergy.com; Bratcher, Mike, EMNRD; Terry_gregston@nm.blm.gov
Subject: Re: Closure Request Turner B #118

Received these results late yesterday and reviewed them last night. The site is good to close for the BLM pending like approval from the OCD.

Terry Gregston
Environmental Protection Specialist
Bureau of Land Management
620 E. Greene St.
Carlsbad, NM 88220

Office (575) 234-5958
Cell (575) 361-2635
Fax (575) 234-5927

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

"Vernon Black" <vernon@hungry-horse.com>

To <Terry_gregston@nm.blm.gov>, "Bratcher, Mike, EMNRD"
<mike.bratcher@state.nm.us>

06/22/2011 07:58 AM

cc <dpotter@linenergy.com>

Subject Closure Request Turner B #118

Good morning,

Please see the attached lab results from the confirmation sampling at Linn's Turner B #118. All contaminant levels appear to be at or below closure levels. I request permission to to line the pit area and back fill the all open excavations with clean material and re-seed the area.

Thanks,
Vernon

From: Celey Keene [<mailto:celey.keene@cardinallabsnm.com>]
Sent: Tuesday, June 21, 2011 3:28 PM
To: 'Vernon Black'; Terry Gregston
Subject: TURNER B 118

THANK YOU,

Celey Keene
Lab Director
Cardinal Laboratories
101 East Marland
Hobbs, NM 88240
T: (575) 393-2326
F: (575) 393-2476
e-mail: celey.keene@cardinallabsnm.com

[attachment "H101260 HHE.pdf" deleted by Terry G Gregston/CFO/NM/BLM/DOI]