

Received 2/27/2017
 NMOCD Dist 2

District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 S. First St., Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

DAB1706039430 OPERATOR Initial Report Final Report

Name of Company	Devon Energy Production Company <i>4137</i>	Contact	Steve McGlasson, Construction/Facilities Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-703-2741
Facility Name	Laguna Salado South #1	Facility Type	Gas
Surface Owner	Federal	Mineral Owner	Federal
		API No	30-015-26407

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	22	23S	29E	2030	North	1980	West	Eddy

Latitude: N 32.2922554

Longitude: W -103.9748001

NATURE OF RELEASE

Type of Release	Produced Water & Oil	Volume of Release	128 BBLS PW & 2BBLS Oil	Volume Recovered	128 BBLS PW & 2BBLS Oil
Source of Release	Basic Sediment & Water (BS&W) valve	Date and Hour of Occurrence	2/15/2017 @ 3:00pm	Date and Hour of Discovery	2/15/2017 @ 3:00pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	BLM-Shelly Tucker OCD-Mike Bratcher		
By Whom?	Aaron Kidd, Assistant Construction Foreman	Date and Hour	BLM-2/16/2017 @ 10:30am OCD-2/16/2017 @ 10:15am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully.*
 N/A

Describe Cause of Problem and Remedial Action Taken.*
 Construction crews were replacing and updating nozzles and Basic Sediment & Water valves at the Laguna Salado South #1. The BS&W split causing a release of 128 BBLS produced water and 2 BBLS oil into the lined containment. The remaining fluids in the tank were removed by vacuum truck to prevent any further release.

Describe Area Affected and Cleanup Action Taken.*
 128 BBLS of produced water and 2 BBLS of oil were released from a BS&W valve into lined containment. All 128 BBLS of produced water and 2 BBLS of oil remained in lined containment. A vacuum truck was dispatched and recovered all 128 BBLS produced water and 2 BBLS oil. The liner was inspected for holes and none were found. No further action is necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sarah Gallegos-Troublefield</i>	OIL CONSERVATION DIVISION	
Printed Name: Sarah Gallegos-Troublefield	<i>[Signature]</i> Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: <i>2/28/17</i>	Expiration Date: <i>N/A</i>
E-mail Address: Sarah.Gallegos-Troublefield@dvn.com	Conditions of Approval: SEE BELOW:	Attached <input type="checkbox"/>
Date: 2/27/2017	Phone: 575.748.1864	

* Attach Additional Sheets If Necessary

COA: It is OCD's understanding that all impacted material has been removed/replaced, the liner cleaned and inspected for integrity.

2RP- 4130

Bratcher, Mike, EMNRD

From: Gallegos-Troublefield, Sarah <Sarah.Gallegos-Troublefield@dvn.com>
Sent: Monday, February 27, 2017 1:01 PM
To: Tucker, Shelly; jamos@blm.gov; Weaver, Crystal, EMNRD; Bratcher, Mike, EMNRD
Cc: Fulks, Brett; Shoemaker, Mike
Subject: Laguna Salado South 1_128 BBLS PW & Oil_Initial & Final C-141
Attachments: Laguna Salado South 1_128 BBLS PW 2 BBLS Oil_Initial Final C-141.doc; Laguna Salado South_128 BBLS PW & 2BBLS Oil_2-15-17_GIS Image.pdf

Good Morning,

Please find attached the Initial C-141 and GIS Image of the Laguna Salado South 1 release of 128 BBLS produced water and 2 BBLS Oil that occurred on 2/15/2017. Please be advised that the blue dot on the GIS Image represents the approximate location of the origin of release.

Please contact me with any questions you may have.

Thank you very much and have a wonderful day.

Respectfully,

Sarah Gallegos-Troublefield
Field Admin Support
Production

Devon Energy Corporation
P.O. Box 250
Artesia, NM 88211
575 748 1864 Direct Line



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.