

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

#AB1706648895 Release Notification and Corrective Action
NAB1706649042 OPERATOR Initial Report Final Report

Name of Company <i>Enterprise Field Services, LLC 1000347</i>	Contact <i>Alena Miro</i>
<i>PO Box 4324, Houston, TX 77210</i>	Telephone No. <i>575-628-6802</i>
Facility Name <i>1009 Pipeline</i>	Facility Type: <i>Natural Gas Pipeline</i>
Surface Owner <i>BLM</i>	Mineral Owner <i>NA</i>
	Lease No. <i>NA</i>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>E</i>	<i>35</i>	<i>22S</i>	<i>29E</i>	<i>85</i>	<i>South</i>	<i>477</i>	<i>West</i>	<i>Eddy</i>

Latitude: *N 32.349122* Longitude: *W -103.962368*

NATURE OF RELEASE


Type of Release <i>Natural Gas and Pipeline Liquids</i>	Volume of Release: <i>2587 MSCF and 35 bbls of pipeline liquids</i>	Volume Recovered: <i>NA</i>
Source of Release <i>Pipeline release</i>	Date and Hour of Occurrence <i>11/28/2016 @ 11:43 MST</i>	Date and Hour of Discovery <i>11/28/2016 @ 11:43 MST</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Mike Bratcher</i>	
By Whom? <i>Alena Miro</i>	Date and Hour <i>11/28/2016 @ 14:51 MST</i>	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <i>35 bbls of pipeline liquids</i>	

If a Watercourse was Impacted, Describe Fully.*
Pipeline liquids were released into a salt waterbody on the Tamarisk Flat. The salt waterbody is a fully enclosed natural depression with no outlet to navigable waters.

Describe Cause of Problem and Remedial Action Taken.*
Natural gas and pipeline liquids were released due to a pipeline leak. The pipeline segment was isolated, blown down, and repaired following a standard one-call. Approximately 35 bbls of liquid were noted on the ROW.

Describe Area Affected and Cleanup Action Taken.*
A liquid spill of approximately 35 bbls occurred as part of the leak. Remediation actions will follow the Enterprise Products, General Release Notification, Response and Remediation Plan (March 9, 2015).

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: <i>Jon E. Fields</i>	Approved by District Supervisor: 	
Title: <i>Director, Field Environmental</i>	Approval Date: <i>3/7/17</i>	Expiration Date: <i>NIA</i>
E-mail Address: <i>jefields@eprod.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: _____ Phone: <i>713-381-6684</i>		

* Attach Additional Sheets If Necessary

2 RP-4137

Bratcher, Mike, EMNRD

From: Nolan, Shiver <SNolan@eprod.com>
Sent: Friday, December 2, 2016 10:48 AM
To: Bratcher, Mike, EMNRD; Randy Pair (rpair@blm.gov); Fernando Banos (fbanos@blm.gov)
Cc: Miro, Alena; Ferguson, Dina
Subject: Eddy County Initial Report - 1009 Pipeline
Attachments: Eddy County C-141 1009 Pipeline (12-1) December 2016.pdf; Eddy County C-141 1009 Pipeline (12-1) December 2016.pdf

Attached is the initial report. Should you need additional information, please contact Ms. Alena Miro.

Shiver J. Nolan
Sr. Compliance Administrator

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.