

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**NM OIL CONSERVATION**  
State of New Mexico  
ARTESIA DISTRICT  
Energy Minerals and Natural Resources  
MAR 08 2017  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**NAB1706938037**

**OPERATOR**  Initial Report  Final Report

Name of Company EOG Y Resources, Inc.	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 <sup>th</sup> Street	Telephone No. 575-748-1471	
Facility Name Tombstone BMB State #1	Facility Type Battery	

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-36315
--------------------------	--------------------------	-------------------------

**LOCATION OF RELEASE**

Unit Letter D	Section 12	Township 25S	Range 29E	Feet from the 660	North/South Line North	Feet from the 330	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.15018 Longitude 103.94558

**NATURE OF RELEASE**

Type of Release Oil & Produced Water	Volume of Release 35 B/PW	Volume Recovered 35 B/PW
Source of Release Heater Treater	Date and Hour of Occurrence 2/19/2017; AM	Date and Hour of Discovery 2/19/2017; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/EOG Resources, Inc.	Date and Hour 2/20/2017; AM * 2/20/17 e-mail 7:22am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A hole developed in the bottom of the heater treater, causing the release. Vacuum truck(s) and roustabout crews were called.

Describe Area Affected and Cleanup Action Taken.\*

An approximate area of 50'X 50'. The valves were closed, vacuum trucks were called and a roustabout crew was called to repair the heater. Impacted gravel was excavated /hailed to a NMOCD approved facility. The release occurred within a lined/bermed battery where the liner has not been compromised and is integrally sound. Depth to Ground Water: 50-99' (approximately 60', Section 10, T25S-T29E, per the NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on repairs, impacted gravel removed excavated and all produced water recovered, EOG Y Resources, Inc. requests closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Asher	Approved by Environmental Specialist: 	
Title: Environmental Supervisor	Approval Date: 3/10/17	Expiration Date: NA
E-mail Address: Robert.Asher@egoresources.com	Conditions of Approval: SEE Attached	Attached <input checked="" type="checkbox"/>
Date: March 7, 2017	Phone: 575-748-4217	2RP- FINAL

\* Attach Additional Sheets If Necessary

2RP-4138

RE: EOG Y Resources \* Tombstone BMB St 1 \* 30-015-36315

Produced fluid release into a lined containment on 2/19/2017.

35 bbls released with 35 bbls recovered

It is OCD's understanding that the containment has been cleaned and the liner has been inspected for integrity.

Mike Bratcher  
NMOCD District 2  
Artesia, NM

## **Bratcher, Mike, EMNRD**

---

**From:** Bob Asher <Bob\_Asher@eogresources.com>  
**Sent:** Monday, February 20, 2017 7:22 AM  
**To:** Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; NMSLO (Carlsbad/Ion Dolly) (idolly@slo.state.nm.us); NMSLO (Hobbs/Amber Groves); NMSLO (Hobbs/Mathew Hagman) (mhagman@slo.state.nm.us); NMSLO (Roswell/Mark Najanjo) (mnaranjo@slo.state.nm.us); NMSLO (Santa Fe/Dana Vackar Strang) (dvstrang@slo.state.nm.us)  
**Cc:** Amber Griffin; Chase Settle; Katie Parker; Veronica Alvarado  
**Subject:** Release Notification (Tombstone BMB State #1)

**EOG Y Resources, Inc. is reporting a release at the following location (2/19/2017, approximately 12:40 PM).**

Tombstone BMB State #1  
30-015-36315  
660 FNL & 330 FWL (UL-D)  
Section 12, T25S-R29E  
Eddy County, New Mexico

**Released: 35 B/PW; Recovered: 35 B/PW.**

Cause of the release was from a possible hole in a heater treater within the battery. **The release was contained within a bermed/lined battery, the liner is intact and in very good condition.** Vacuum truck(s) and roustabout crews were called. All released produced water was recovered and repairs completed.

A Form C-141 with complete information will be submitted.

Thank you.

**Robert C. "Bob" Asher**  
**Environmental Supervisor**  
**Safety & Environmental Department**  
**EOG Resources, Inc.**  
**Artesia Division Office**  
105 S. 4<sup>th</sup> Street  
Artesia, NM 88210  
575-748-4217 (Office)  
575-365-4021 (Cell)  
**EOG Safety Begins With YOUR Safety**

