

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

APR 12 2017

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
RECEIVED accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1710730038

OPERATOR

Initial Report Final Report

Name of Company EOG Y Resources, Inc.	25575	Contact Robert Asher
Address 104 S. 4 th Street		Telephone No. 575-748-1471
Facility Name Gazelle AHG Federal #2		Facility Type Battery

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-26441
--------------------------	--------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter P	Section 16	Township 20S	Range 29E	Feet from the 1000	North/South Line South	Feet from the 5	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	--------------------	------------------------	----------------

Latitude 32.56895 Longitude 104.07154

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 5 B/PW	Volume Recovered 0 B/PW
Source of Release Gun Barrel	Date and Hour of Occurrence 3/15/2017; AM	Date and Hour of Discovery 3/15/2017; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour NB/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Malfunction with the PVC piping going into the gun barrel, causing the release. Vacuum truck(s) and roustabout crews were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 5' x 25' within the bermed battery. The PVC was repaired. The impacted soils were excavated and hauled for disposal. **Depth to Ground Water: 50-99'** (approximately 90', Section 28, T20S-R29E, per the NMOSE), **Wellhead Protection Area: No, Distance to Surface Water Body: >1000'**, **SITE RANKING IS 10.** Based on the small; released amount and that all impacted soils have been excavated and taken to an approved NMOCD facility, EOG Y Resources, Inc. requests closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by Environmental Specialist: 	
Title: Environmental Supervisor	Approval Date: <u>4/17/17</u>	Expiration Date: <u>N/A</u>
E-mail Address: Robert_Asher@eogresources.com	Conditions of Approval: 2RP- <u>FINAL</u>	Attached <input type="checkbox"/>
Date: April 12, 2017	Phone: 575-748-4217	

* Attach Additional Sheets If Necessary

2RP-4170

Bratcher, Mike, EMNRD

From: Bob Asher <Bob_Asher@eogresources.com>
Sent: Wednesday, April 12, 2017 10:49 AM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD
Cc: stucker@blm.gov
Subject: Form C-141, Initial/Final Report (Gazelle AHG Federal #2)
Attachments: Gazelle AHG Federal #2 (Form C-141, InitialFinal Report, 3-15-2017).pdf

Thank you,

Robert C. "Bob" Asher
Environmental Supervisor
Safety & Environmental Department
EOG Resources, Inc.
Artesia Division
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)
EOG Safety Begins With YOUR Safety

