

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT
State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAY 25 2017

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1714 1249151

OPERATOR Initial Report Final Report

Name of Company Devon Energy Production Company <i>LD137</i>		Contact Matt Nettles, Production Foreman	
Address 6488 Seven Rivers Hwy Artesia, NM 88210		Telephone No. 575-513-5767	
Facility Name Cotton Draw Unit SWD 181		Facility Type Salt Water Disposal	
Surface Owner State	Mineral Owner State	API No 30-015-41649	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	36	24S	31E	1568'	North	1189'	East	Eddy

Latitude: 32.1767349

Longitude: -103.7268524

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10bbls	Volume Recovered 10bbls
Source of Release Fitting on water filter trailer	Date and Hour of Occurrence May 20, 2017 @ 3:05 PM	Date and Hour of Discovery May 20, 2017 @ 3:05 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos, BLM Mike Bratcher, OCD	
By Whom? Mike McMahan, Assistant Production Foreman	Date and Hour Jim Amos, BLM May 20, 2017 @ 7:31 PM Mike Bratcher, OCD May 22, 2017 @ 10:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
A 6" fitting broke off the filter trailer due to corrosion. The facility inlet was immediately shut and locked out to stop the release. Repairs were made and the unit is back in operation.

Describe Area Affected and Cleanup Action Taken.*
Approximately 10bbls produced water was released into lined containment. A vacuum truck was dispatched and recovered all 10bbls of produced water from lined containment. The containment is located on the Northeast side of location and the liner and containment were visually inspected for holes and none were found. No further action is necessary

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Signed By: <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: <i>5/26/17</i>	Expiration Date: <i>N/A</i>
E-mail Address: Sheila.fisher@dvn.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 5/22/17 Phone: 575.748.1829		

New forms can be found in the New Mexico State Website in forms: <http://www.emnrd.state.nm.us/OCD/forms.html>

* Attach Additional Sheets If Necessary

2RP-4228

Bratcher, Mike, EMNRD

From: Fisher, Sheila <Sheila.Fisher@dvn.com>
Sent: Thursday, May 25, 2017 10:16 AM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Amber Groves (agroves@slo.state.nm.us)
Cc: Shoemaker, Mike; Fulks, Brett; Nettles, Matt; Carter, Ray; McMahan, Mike
Subject: Cotton Draw Unit SWD 181_10bbl pw_5.20.17
Attachments: Cotton Draw Unit SWD 181_10bbl pw_Initial Final C-141_5.20.17.doc; Cotton Draw Unit SWD 181_10bbl pw_pic 1 of 3_5.20.17.jpg; Cotton Draw Unit SWD 181_10bbl pw_pic 2 of 3_5.20.17.jpg; Cotton Draw Unit SWD 181_10bbl pw_pic 3 of 3_5.20.17.jpg

Good Morning,

Attached please find the Initial & Final C-141 and GIS Image for the 10bbl produced water release at the Cotton Draw Unit SWD 181 on 5.20.17.

If you have any questions please feel free to contact me.

Thank you,

Sheila Fisher
Field Admin Support
Production
B-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.