

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**NAB1715035797**

**OPERATOR**

Initial Report  Final Report

<b>Name of Company</b> Devon Energy Production Company <i>6137</i>	<b>Contact</b> Danny Velo, Production Foreman
<b>Address</b> 6488 Seven Rivers Hwy Artesia, NM 88210	<b>Telephone No.</b> 575.703.3360
<b>Facility Name</b> Coral PWU 28 4H	<b>Facility Type</b> Oil Well

<b>Surface Owner State</b>	<b>Mineral Owner State</b>	<b>API No</b> 30-015-39328
----------------------------	----------------------------	----------------------------

**LOCATION OF RELEASE**

Unit Letter P	Section 28	Township 19S	Range 29E	Feet from the 330	North/South Line FSL	Feet from the 990	East/West Line FEL	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	----------------

**Latitude:** 32.625395 **Longitude:** -104.074521

**NATURE OF RELEASE**

<b>Type of Release</b> Produced Water (PW)	<b>Volume of Release</b> 20BBLS	<b>Volume Recovered</b> 0BBLS
<b>Source of Release</b> Hole in the fire tubing on heater treater	<b>Date and Hour of Occurrence</b> 7/14/2016 @ 10:00AM	<b>Date and Hour of Discovery</b> 7/14/2016 @ 10:00AM
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> OCD-Mike Bratcher	
<b>By Whom?</b> Jesse Armendariz, Assistant Production Foreman	<b>Date and Hour</b> OCD-Mike Bratcher-7/14/2016@ 11:30AM	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse</b> N/A	

**If a Watercourse was Impacted, Describe Fully.\***  
N/A

**Describe Cause of Problem and Remedial Action Taken.\***  
20 BBLS of PW was released due to hole in the fire tubing on heater treater from normal wear and tear resulting in a fire on location. Loco Hills Fire Department was contacted and extinguished the fire. All tubing and casing on the Coral 28- 1, 2, 3, 4, 5, 6, and 7 were shut in and the inlet and outlet valves on the vessels from the production heater were also shut in to prevent further release. All battery power was shut off at disconnect and Supervisory Control and Data Acquisition Tech (SCADA) disconnected battery power to SCADA Panel. Repairs will be made.

**Describe Area Affected and Cleanup Action Taken.\***  
20BBLS PW released from a hole in the fire tubing on the heater treater. 0BBLS PW were recovered. The North East Side of location was where the fire occurred originating from the heater treater and the approximate total affected area is 113ft by 90ft all contained on pad. An environmental company will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dana DeLaRosa</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Dana DeLaRosa	Signed By <i>Mike Bratcher</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	Approval Date: <i>5/26/17</i> Expiration Date: <i>N/A</i>
E-mail Address: <i>dana.delarosa@dvn.com</i>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: 7/18/2016 Phone: 575.746.5594	<b>SUBMIT REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary

LATER THAN: *6/26/17*

Note: Late entry by OCD

*2RP-4229*

## Bratcher, Mike, EMNRD

---

**From:** DeLaRosa, Dana <Dana.DeLaRosa@dvn.com>  
**Sent:** Monday, July 18, 2016 9:07 AM  
**To:** Bratcher, Mike, EMNRD; agroves@slo.state.nm.us  
**Subject:** Coral PWU 28 4H\_20BBLS PW\_7.14.16  
**Attachments:** Coral PWU 28 #4H\_20BBLS PW, 7.14.16\_Intial C141.doc; Coral PWU 28 #4H\_20BBLS PW, 7.14.16\_GIS Image.pdf; Coral PWU 28 4H\_Pic 1 of 2.jpg; Coral PWU 28 4H\_Pic 2 of 2.jpg

Good morning,

Attached is the Initial C141, GIS Image and photos for the 20BBL produced water release that occurred on 7.14.2016 at the Coral PWU 28 4H. The red dot on the GIS Image represents the approximate origin of release.

Thank you,

*Dana DeLaRosa*

Field Admin Support  
Production  
B-Schedule



Devon Energy Corporation  
PO Box 250  
Artesia, NM 88211  
575-746-5594

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.