

District I
1225 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Brothers Production Company, Inc.	Contact	Danny M. Brock
Address	P.O. Box 7515, Midland, TX 79708	Telephone No	432-682-2516.
Facility Name	Denton SWD line	Facility Type	SWD line from Battery

Surface Owner	Darr Angel	Mineral Owner	Brothers Production Company, Inc.	Lease No	168980
---------------	------------	---------------	-----------------------------------	----------	--------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	11	15-S	37E	1980	South	1980	East	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	60	Volume Recovered	55
Source of Release	SWD line from Battery	Date and Hour of Occurrence	3/28/06 1:00PM	Date and Hour of Discovery	1:30 PM 3/28/06
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gary w/ Hobbs OCD			
By Whom?	Danny M. Brock	Date and Hour	3-28-06 2:30 PM CDT		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Americo had installed a new SWD line to the SWD. When our line was backfilled, a rock knocked a hole in our SWD trunkline. The line was shut in and a vacuum truck was used to recover free-standing water.

Describe Area Affected and Cleanup Action Taken.*

Most of the discharge was contained in the bar ditch of the road. We used a vacuum truck to pick up the produced water. A small portion of pasture was affected. This area will be tilled and fertilized.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.



Signature: <i>Danny M. Brock</i>	OIL CONSERVATION DIVISION	
Printed Name: Danny M. Brock	Approved by District Supervisor:	
Title: Production Superintendent	Approval Date:	Expiration Date:
E-mail Address: dannyb@brothersproduction.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3-29-06	Phone: 432-682-2516	

* Attach Additional Sheets If Necessary

*called Danny Brock - 4-3-06 0750 explained leak over 100 bbl ~150 bbl of rain ~1000 ft
OCD req. rem. plan in 30-days. Brothers 2936 FPAC 0609651715 PPACD 0609652114
PPACD 0609651812*