

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised March 17, 1999

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**  Initial Report  Final Report

Name of Company <i>XTO Energy</i>	Contact <input type="checkbox"/> <i>Guy Pearce</i>
Address <i>P.O. Box 700 Eunice N.M. 88231</i>	Telephone No. <input type="checkbox"/> <i>(505) 441-1637</i>
Facility Name <i>Bridges STATE #12 Battery</i>	Facility Type <input checked="" type="checkbox"/> <i>Tank Battery</i>
Surface Owner <i>STATE of New Mexico</i>	Mineral Owner _____ Lease No. <input type="checkbox"/> <i>67550</i>

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County <input type="checkbox"/>
<i>G</i>	<i>26</i>	<i>17s</i>	<i>34E</i>					

*93'*

**NATURE OF RELEASE**

Type of Release <i>Crude Oil</i>	Volume of Release <i>304 bbls</i>	Volume Recovered <input type="checkbox"/> <i>210 bbls</i>
Source of Release <i>2" circulating line on back of Tank</i>	Date and Hour of Occurrence _____	Date and Hour of Discovery <input type="checkbox"/> <i>9:00 am 3/29/06</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Pat Caperton NMOCD</i>	
By Whom? <input checked="" type="checkbox"/> <i>Guy Pearce</i>	Date and Hour <i>3/29/06 9:45 am</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* *External corrosion on 2" line coming off the back of scabbl oil stock Tank caused line to leak out 304 bbls of oil. 210 bbls of oil was recovered and put back into oil tanks. 2" of contaminated soil was scraped up with a back hoe and put on plastic. Soil sampling is being conducted to determine further contamination.*

Describe Area Affected and Cleanup Action Taken.\*

*80' x 80' area on south east corner of battery (pasture)  
35' x 100' area in front of tanks and road leading into Battery.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.



Signature: <i>Guy Pearce</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <i>Guy Pearce</i>		Approved by <input type="checkbox"/> District Supervisor:	
Title: <i>Production Foreman</i>		Approval Date:	Expiration Date:
Date: <i>3/29/06</i>	Phone: <i>(505) 441-1637</i>	Conditions of Approval:	Attached <input type="checkbox"/>

Attach Additional Sheets If Necessary

*facility - FPAC0609 652826  
incident - NPAC0609 652901  
application - FPAC0609 653142  
XTO - 5380*