


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Pure Resources	Contact Danny Lovell
Address P.O. Box 1949 Eunice NM 88231	Telephone No. 505-394-1242
Facility Name Brunson Argo Bty #3	Facility Type- Production

Surface Owner Pricilla West	Mineral Owner-State	Lease No.
-----------------------------	---------------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	9	22s	37e					Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release 25 BO/10BW	Volume Recovered 23 BO/7 BW
Source of Release- 300 bbl oil tank	Date and Hour of Occurrence 3/12/06	Date and Hour of Discovery 3/12/06 7:30 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gary Wink	
By Whom? Larry Williams	Date and Hour 3/12/06 3:30pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Hole in bottom of 300 bbl stock tank. No visible signs on exterior of tank indicating any problems with integrity of tank. Tank will be cleaned and replaced with a new tank.

Describe Area Affected and Cleanup Action Taken.* Fluid was contained inside berm at battery. Standing fluid was vacuumed up and hydrocarbon affected soil will be scraped up and taken to land farm. Depth to ground water ~100'.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Larry Williams	Approved by District Supervisor:	
Title: HES Champion	Approval Date:	Expiration Date:
E-mail Address: lcwl@chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/13/06	Phone: 394-1237	

* Attach Additional Sheets If Necessary

facility - pPAC 0609 653608
incident - nPAC 0609 653689
application - pPAC 0609 653912