

JUL 13 2017

Form C-141
Revised August 8, 2011

NMDistrict I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

FAB1719929254 OPERATOR Initial Report Final Report
DAB1719929393

Name of Company	Enterprise Field Services, LLC	Contact	Alena Miro
	PO Box 4324, Houston, TX 77210	Telephone No.	575-628-6802
Facility Name	Paloma Pipeline Blowdown	Facility Type:	Natural Gas Pipeline
Surface Owner	State of New Mexico	Mineral Owner	NA
		Lease No.	NA

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	8	21S	35E	220	North	540	East	Eddy

Latitude: N 32.489217 Longitude: W -103.387220

NATURE OF RELEASE

Type of Release	Natural Gas	Volume of Release:	329 MSCF	Volume Recovered:	NA
Source of Release	Pipeline blowdown	Date and Hour of Occurrence	7/7/2017 @ 15:50 MST	Date and Hour of Discovery	7/7/2017 @ 16:57 MST
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	OCD District 2 - Emergency Notification Hotline		
By Whom?	Alena Miro	Date and Hour	7/8/2017 at 15:15 MST		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* Natural gas was released from the pipeline to install over pressure protection for the pipeline. The pipeline segment was isolated and blown down and returned to service after the installation.					
Describe Area Affected and Cleanup Action Taken.* N/A					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				OIL CONSERVATION DIVISION	
Printed Name:	Jon E. Fields	Approved by District Supervisor:			
Title:	Director, Field Environmental	Approval Date:	7/17/17	Expiration Date:	N/A
E-mail Address:	jefields@eprod.com	Conditions of Approval:	FINAL	Attached	<input type="checkbox"/>
Date:	7/13/2017	Phone:	713-381-6684		

* Attach Additional Sheets If Necessary

Please refer to the New Mexico Oil Conservation Division Website for updated form(s) at:
<http://www.emnrd.state.nm.us/OCD/forms.html>
Thank you

229-4294

7/14/17 AB

Bratcher, Mike, EMNRD

From: Nolan, Shiver <SNolan@eprod.com>
Sent: Thursday, July 13, 2017 2:56 PM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Amber Groves
(agroves@slo.state.nm.us)
Cc: Miro, Alena; Ferguson, Dina
Subject: Eddy County Paloma Pipeline
Attachments: Eddy County C-141 Paloma PL Blowdown (7-7) July 2017.pdf

Attached is a C-141 for a blowdown – please contact Alena Miro if you need additional information.

Shiver Nolan
Sr. Compliance Administrator

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.