




AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pCS1716332215

3RP - 1049

WPX ENERGY PRODUCTION, LLC

8/31/2017

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company WPX Energy Production, LLC	Contact Deborah Watson
Address PO Box 640	Telephone No. 505-333-1880
Facility Name WLU Remote #2	Facility Type
Surface Owner Federal	Mineral Owner Federal (NMNM-025830)
API No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	18	23N	08W	231	North	820	West	San Juan


Latitude N36.23333 Longitude W107.72820

NATURE OF RELEASE

Type of Release produced water	Volume of Release 15 bbl	Volume Recovered 15 bbl
Source of Release below grade tank within lined secondary containment	Date and Hour of Occurrence	Date and Hour of Discovery 8/1/17 07:00 hrs
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? N/A	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Localized heavy rain.		
Describe Area Affected and Cleanup Action Taken.* <ul style="list-style-type: none"> • A spec truck recovered 15 bbl produced water, 100% recovery. • All fluids remained within secondary lined containment. • Tank and containment were washed. • Inspection of liner conducted by Deborah Watson on 8/10/17 at 7:10 am-liner in good condition/no tears observed. • No further actions recommended. 		

OIL CONS. DIV DIST. 3
AUG 1 1 2017

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Deborah Watson	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: 8/31/2017	Expiration Date:
E-mail Address: deborah.watson@wpxenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 08/10/2017	Phone: 505-333-1880	

* Attach Additional Sheets If Necessary

NVF1724340995