

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company <b>Myco Industries, Inc.</b>	Contact <b>Hannah Palomin</b>
Address <b>P.O. Box 840</b>	Telephone No. <b>505.748.4288</b>
Facility Name <b>Sharbro Federal #2 Battery</b>	Facility Type <b>Tank Battery - Produced Water Tank</b>
Surface Owner	Mineral Owner <b>US</b>
Lease No. <b>NM-62223</b>	


**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>H</b>	<b>17</b>	<b>23S</b>	<b>32E</b>	<b>App. 2310'</b>	<b>North</b>	<b>App. 660'</b>	<b>East</b>	<b>Lea</b>

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release <b>Produced Water &amp; trace of oil</b>	Volume of Release <b>25+/- bbls</b>	Volume Recovered <b>25+/- bbls</b>
Source of Release <b>Lightening strike to water tank</b>	Date and Hour of Occurrence <b>Approx. late evening 3/28/06</b>	Date and Hour of Discovery <b>Late evening 3/28/06</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* <b>No, per NMOCD map, depth to groundwater is greater than 400'</b>		
Describe Cause of Problem and Remedial Action Taken.* <b>Lightening strike to 500 bbl fiberglass produced water tank. Spill contained and affected caliche on location was moved to certified landfill.</b>		
Describe Area Affected and Cleanup Action Taken.* <b>Tank Battery pad. Minor impact to top soil adjacent to pad. Spill contained and affected caliche and topsoil was moved to certified landfill.</b>		



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Hannah Palomin</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Hannah Palomin</b>	Approved by District Supervisor:	
Title: <b>Engr/Land Tech</b>	Approval Date:	Expiration Date:
E-mail Address: <b>hannah@mycoinc.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>3/30/06</b>	Phone: <b>505.748.4288</b>	

\* Attach Additional Sheets If Necessary

*Myco-15445  
facility #PAC0610840006*

*incident - #PAC0610840170  
application - #PAC0610840322*