

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JAN 22 2018

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1802429248

OPERATOR

Initial Report Final Report

Name of Company: XTO Energy / <i>Barco 240737</i>	Contact: Kyle Littrell
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No: 432-221-7331
Facility Name: Big Eddy Unit DI5 Tank Battery (API for BEU DI5 #004H)	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No: 30-015-40397	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	27	20S	31E	2530	North	1700	East	Eddy

Latitude 32.544507° Longitude -103.854020° NAD83

NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	45 bbls	Volume Recovered	45 bbls
Source of Release	Oil Tanks	Date and Hour of Occurrence	1/7/2018 time unknown	Date and Hour of Discovery	1/8/2018 12 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher/Crystal Weaver (NMOCD), Shelly Tucker/Jim Amos (BLM)		
By Whom?	Amy Ruth	Date and Hour:	1/8/2018 7:17 am by email		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Oil tanks overflowed into lined containment due to hauling company falling behind schedule.

Describe Area Affected and Cleanup Action Taken.*
The release affected the impermeable lined containment surrounding the oil and produced water tanks at the south end of the facility. No fill material was located inside containment. A XTO EHS Coordinator who is competent in the operation, maintenance, and inspection of all on-site equipment and facilities visually inspected the containment and verified that there was no visual evidence of a liner breach. All free-standing liquids were recovered from the containment and the containment and equipment were power washed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: Kyle Littrell	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Coordinator	Approval Date: <i>1/25/18</i>	Expiration Date: <i>NIA</i>
E-mail Address: Kyle.Littrell@xtoenergy.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/> <i>2RP-4587</i>
Date: 1/22/2018 Phone: 432-221-7331		

* Attach Additional Sheets If Necessary

1/25/18 AB


Bratcher, Mike, EMNRD

From: Littrell, Kyle <Kyle_Littrell@xtoenergy.com>
Sent: Monday, January 22, 2018 1:57 PM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Tucker, Shelly; Jim Amos
Cc: Ruth, Amy; Foust, Bryan; McSpadden, Wes; Sanders, Toady
Subject: Initial-Final C-141 - BEU DI5 Battery 1-8-18
Attachments: Initial-Final C-141 BEU DI5 Battery 1-8-18.pdf

Good Afternoon,

Please find attached the initial/final form C-141 for the release event at the referenced site. Statement and photos are attached per NMOCD request. Please call with any questions or concerns. Thank you. -Kyle







Kyle Littrell

EH&S Coordinator

XTO Energy Inc.

Delaware Division

Phone:(432)-221-7331 | Mobile:(970)-317-1867

kyle_littrell@xtoenergy.com

An **ExxonMobil** Subsidiary

Bratcher, Mike, EMNRD

From: Ruth, Amy <Amy_Ruth@xtoenergy.com>
Sent: Monday, January 8, 2018 7:17 AM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Shelly Tucker; Jim Amos
Cc: Littrell, Kyle; Sanders, Toady; Foust, Bryan; McSpadden, Wes
Subject: Release Notification - Big Eddy Unit D15 Tank Battery (API 30-015-40397)

Good morning,

This is sent as notification that early this morning XTO discovered a release of fluids from the referenced facility (API for BEU D15 #004H) of a volume in excess of 25 barrels. Details will be provided with a form C-141. Please call with any questions or concerns. Thank you.

Respectfully,

Amy Ruth
432-661-0571

Sent from my iPhone