

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

JAN 22 2018

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.  
**RECEIVED**

**Release Notification and Corrective Action**

*NAB1802928387*

**OPERATOR**

Initial Report  Final Report

Name of Company <i>Devon Energy Production Company</i> <i>U137</i>	Contact <i>Aaron Kidd; Foreman Technical Services</i>	
Address <i>6488 Seven Rivers Hwy Artesia, NM 88210</i>	Telephone No. <i>575-513-1770</i>	
Facility Name <i>Parkway West SWD 1</i>	Facility Type <i>Salt Water Disposal</i>	
Surface Owner State	Mineral Owner State	API No. <i>30-015-40835</i>

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	27	19S	29E					Eddy

Latitude *\_32.635521 N\_* Longitude *-104.069517 W\_* NAD83

**NATURE OF RELEASE**

Type of Release <i>Oil</i>	Volume of Release <i>39 BBLs</i>	Volume Recovered <i>39 BBLs</i>
Source of Release <i>Tank Overflow</i>	Date and Hour of Occurrence <i>1.8.2018 @ 9:15 AM MST</i>	Date and Hour of Discovery <i>1.8.2018 @ 9:15 AM MST</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>OCD: Mike Bratcher &amp; Crystal Weaver SLO: Amber Groves</i>	
By Whom? <i>Mike Shoemaker; EHS Professional</i>	Date and Hour <i>OCD and BLM 1.09.2018 @ 8:49 AM MST</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <i>N/A</i>	

If a Watercourse was Impacted, Describe Fully.\*  
*N/A*

Describe Cause of Problem and Remedial Action Taken.\*  
*The SWD facility received a slug of oil from one of the batteries and over flowed the oil tank into the lined SPCC containment ring. The lease operator opened the equalizer valve to the tanks and equalized the fluid level and dispatched a vacuum truck to remove fluids from the lined containment. Approximately 39 bbls of oil was released and approximately 39 bbls oil was recovered.*

Describe Area Affected and Cleanup Action Taken.\*  
*Approximately 39 BBLs of oil were released from oil tank into the lined SPCC containment ring. A vacuum truck was dispatched and recovered approximately 39 bbls oil from the lined containment. Once fluids were removed the liner was visually inspected by Devon field staff for any pinholes or punctures and none were found. Based on this inspection there is no evidence that the spill fluids left containment.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tamala J. Robison</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <i>Tamala J. Robison</i>	Approved by Environmental Specialist: <i>Mike Bratcher</i>	
Title: <i>Field Admin Support</i>	Approval Date: <i>1/25/18</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>Tamala.Robison@dvn.com</i>	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/> <i>2RP-4586</i>
Date: <i>1.9.2018</i> Phone: <i>575-748-0181</i>		

\* Attach Additional Sheets If Necessary

*1/25/18 AB*

**Bratcher, Mike, EMNRD**

---


**From:** Robison, Tamala <Tamala.Robison@dvn.com>  
**Sent:** Monday, January 22, 2018 4:33 PM  
**To:** Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Honea, Tammy  
**Cc:** Shoemaker, Mike; Fulks, Brett  
**Subject:** Parkway West SWD 1\_39bbbs Oil\_1.8.2018  
**Attachments:** Parkway West SWD 1\_39bbl Oil\_1.8.2018.pdf; Parkway West SWD 1\_39BBLS Oil\_1.8.18  
\_Initial\_Final C-141.doc

Good afternoon,

Attached is the Initial Final C-141 and GIS image for the 39BBLS oil release that occurred at the Parkway West SWD 1 on January 8, 2018. The red dot on the GIS image represents the approximate origin of the release.

If you should have any questions please feel free to contact Mike Shoemaker.

Gratefully,



Your message is ready to be sent with the following file or link attachments:

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.



Parkway West SWD 1

39bbl Oil\_1.8.18



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS\_1984\_Web\_Mercator\_Auxiliary\_Sphere  
Prepared by: Tamala Robison  
Map is current as of: 10-Jan-2018



Miles

0 0.01 0.02 0.04 1:1,779

