



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pCS1523130486

3RF - 3

WPX ENERGY PRODUCTION, LLC



January 15, 2018

Charlie Perrin
New Mexico Oil Conservation Division
Energy, Minerals, and Natural Resources
1000 Rio Brazos Road
Aztec, New Mexico 87410

OIL CONS. DIV DIST. 3
JAN 16 2018

RE: Condition of Approval for Extension
Section 30 Recycling Containment and Facility #3RF-3
January 2018 Monthly Report
December 15 – January 12

CS
1/16/18

Dear Mr. Perrin,

Pursuant to Order R-14314, WPX submitted a C-103 for a 6-month extension request for cessation of operations on August 23, 2017, for the Section 30 Recycling Containment and Facility (#3RF-3) located in Section 30, Township 31N, Range 5W, Rio Arriba County, New Mexico. Approval of the 6-month extension was granted by Director David Catanach on August 25, 2017. Conditions of Approval (COA) of the C-103 are listed below. This report is being submitted to satisfy the monthly report requirement.

1.0 Conditions of Approval

Approval of the extension was granted with the following Conditions of Approval:

- 1) Take necessary actions to keep fresh water accumulation within the containment to a minimum and prevent damage from freezing.
- 2) Inspect and take photographs of the Facility weekly.
- 3) In the event of leaks or damage to the Facility, the operator must do the following.
 - a. Notify OCD District III within 72 hours of knowledge of leaks or damage.
 - b. Submit a Corrective Action Plan (CAP) to repair leaks or damage with seven days of notification above.
 - c. Upon OCD's approval of the CAP, complete repairs per the OCD-approved schedule.
- 4) By the 15th of the month, submit monthly reports to OCD District III of inspection results with photographs and progress on CAPs, if any.
- 5) Verify liner integrity before returning the containment to service.

2.0 Weekly Inspections

Attached is a summary of weekly inspections conducted at the containment from December 15 – January 12. Also attached is a photograph log documenting site conditions during December 15 – January 12.

**Section 30 Recycling Containment and Facility
January 2018 Monthly Report**

3.0 Recent Event Summary

- Water in containment as of December 26, 2017. As of January 12, 2018, a small volume of water remains in containment. (See attached photograph log)
- A minimal amount of water was pumped from leak detection between the weeks of December 25 and January 9.
- Personnel continue to search and inspect the liner for any potential areas of concern along the base of the containment.
- WPX transferred operations at the Section 30 Recycling Containment and Facility to Logos Resources II, LLC on January 10, 2018.

The January 2018 Monthly Report is the final monthly report for the Section 30 Recycling Containment and Facility (3RF-#3) submitted by WPX Energy Production, LLC.

Sincerely,



Deborah Watson
Environmental Specialist

Attachments

Figure 1. Weekly Inspection Log Summary

Figure 2. Photograph Log


Section 30 Recycling Facility and Containment Inspection Summary

WEEKLY INSPECTION:

DATE: 12/21/2017 12/28/2017 1/3/2018 1/9/2018

	YES	NO	YES	NO	YES	NO	YES	NO
1. ARE FREEBOARD LEVELS AT 3 feet OR GREATER?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. IS THERE ANY OIL ACCUMLATION ON THE CONTAINMENT?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
3. ARE THERE VISIBLE TEARS IN LINER?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
4. DOES THE NET NEED MAINTENANCE?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
5. IS THE FENCING IN GOOD CONDITION?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. HOUSEKEEPING ISSUES?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
7. POND MEASUREMENT (HEIGHT)	N/A		N/A		N/A		N/A	
8. IS THERE WATER PRESENT IN THE LEAK DETECTION TUBE?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. DEAD WILDLIFE/BIRDS INSIDE CONTAINMENT?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
COMMENTS: (include water quality odor, color, etc.)			Minor volume of water in leak detection		Minor volume of water in leak detection		Minor volume of water in leak detection	
ADDITIONAL OBSERVATIONS:			Water in containment		Water in containment		Water in containment	


WPX Energy Production, LLC
Section 30 Recycling Containment and Facility
January 2018 Monthly Report

WPX Energy Production, LLC	
Section 30 Recycling Containment and Facility	
30-31N-05W Rio Arriba County, New Mexico	
Date: December 21, 2017	
Photograph #1	


WPX Energy Production, LLC	
Section 30 Recycling Containment and Facility	
30-31N-05W Rio Arriba County, New Mexico	
Date: December 21, 2017	
Photograph #2	


WPX Energy Production, LLC
Section 30 Recycling Containment and Facility
January 2018 Monthly Report

WPX Energy Production, LLC	
Section 30 Recycling Containment and Facility	
30-31N-05W Rio Arriba County, New Mexico	
Date: December 21, 2017	
Photograph #3	


WPX Energy Production, LLC	
Section 30 Recycling Containment and Facility	
30-31N-05W Rio Arriba County, New Mexico	
Date: December 28, 2017	
Photograph #4	


WPX Energy Production, LLC
Section 30 Recycling Containment and Facility
January 2018 Monthly Report

WPX Energy Production, LLC	
Section 30 Recycling Containment and Facility	
30-31N-05W Rio Arriba County, New Mexico	
Date: January 3, 2018	
Photograph #5	

WPX Energy Production, LLC	
Section 30 Recycling Containment and Facility	
30-31N-05W Rio Arriba County, New Mexico	
Date: January 3, 2018	
Photograph #6	

WPX Energy Production, LLC
Section 30 Recycling Containment and Facility
January 2018 Monthly Report

WPX Energy Production, LLC	
Section 30 Recycling Containment and Facility Repair	
30-31N-05W Rio Arriba County, New Mexico	
Date: January 3, 2018	
Photograph #7	

WPX Energy Production, LLC	
Section 30 Recycling Containment and Facility	
30-31N-05W Rio Arriba County, New Mexico	
Date: January 12, 2018	
Photograph #8	