

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

MAR 13 2018

RECEIVED

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

FAB1807453570

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company EOG Y Resources, Inc.	Contact Robert Asher
Address 104 S. 4 th Street Artesia NM 88210	Telephone No. 575-748-1471
Facility Name Eagle Creek Gas System	Facility Type Pipe line

Surface Owner Fee	Mineral Owner Fee	API No.
----------------------	----------------------	---------

LOCATION OF RELEASE

Unit Letter D	Section 25	Township 18S	Range 25E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.7235031 Longitude -104.4433899 NAD83

NATURE OF RELEASE


Type of Release Unknown	Volume of Release Unknown Amounts	Volume Recovered Unknown Amounts
Source of Release Unknown	Date and Hour of Occurrence Unknown	Date and Hour of Discovery Unknown
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/EOG Y Resources	Date and Hour March 13, 2018	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*
Upon the reclamation process of the Stark BG #2 Battery the surface owner requested remediation of the impacted area south of the battery. Initial horizontal and vertical delineation samples collected.

Describe Area Affected and Cleanup Action Taken.*
The affected area was approximately 180' X 200'. Horizontal/Vertical delineation samples collected (enclosed). Based off of results, core rig sampling is being scheduled (details to be submitted on a work plan). **Depth to Ground Water: >100' (approximately 158', per NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Signed By 	
Title: Environmental Supervisor	Approved by Environmental Specialist:	
E-mail Address: robert_asher@eogresources.com	Approval Date: 3/13/18	Expiration Date: N/A
Date: March 13, 2018 Phone: 575-748-4217	Conditions of Approval: See attached	Attached 2RP-4659

* Attach Additional Sheets If Necessary