

ENVIRONMENTAL OIL CONSERVATION

ARTESIA DISTRICT

MAR 22 2018

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141
Revised August 8, 2011

HAB1808242680 Release Notification and Corrective Action

NAB1808242819 OPERATOR Initial Report Final Report

Name of Company	Western Refining Pipeline LLC. 248440	Contact	Matthew Krakow
Address	16 CR 5150	Telephone No.	505-632-4169
Facility Name	Golden Spur 36	Facility Type	Crude Pipeline Pig Launcher Site

Surface Owner	Western Refining Pipeline, LLC	Mineral Owner		API No.	
---------------	---	---------------	--	---------	--

BLM land

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	36	26S	R31E					Eddy

Latitude 32.00242741 N Longitude -103.7573891 W

NATURE OF RELEASE

168 gallons = ~4 bbls = ~3.6 bbls
150 gallons


Type of Release	Entegrate IC3710 (pipeline cleaner)	Volume of Release	1000 168 Gallon	Volume Recovered	0 Gallons
Source of Release	Fire	Date and Hour of Occurrence	3/17/18	Date and Hour of Discovery	3/18/18, 8:30am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Gilbert Gerero		
By Whom?	Matthew Krakow	Date and Hour	3/19/18 8:11am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
A fire burned a 350 gallon chemical tank. The tank had 168 gallons of product in it the night of the fire. The chemical tank had secondary containment that captured an estimated 150 gallons of product with an estimated 10-15 gallons released to ground. The rest of the chemical was burned or evaporated as a result of the fire. The fire was already out when the facility operator discovered the burnt tank at the pipeline site.

Describe Area Affected and Cleanup Action Taken.*
An estimated 10-15 gallons of chemical release to the ground at the site. The impacted soil has been excavated.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Matthew Krakow	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: 3/23/18	Expiration Date: N/A
E-mail Address: Matthew.J.Krakow@andevor.com	Conditions of Approval: <i>See attached</i>	Attached: <i>APP-4671</i>
Date: 03/22/18	Phone: (505) 632-4169	

* Attach Additional Sheets If Necessary

Operator/Responsible Party,

The OCD has received the form C-141 you provided on **3/22/18** regarding an unauthorized release. The information contained on that form has been entered into our incident database and remediation case number 2RP-4671 has been assigned. **Please refer to this case number in all future correspondence.**

It is the Division's obligation under both the Oil & Gas Act and Water Quality Act to provide for the protection of public health and the environment. Our regulations (19.15.29.11 NMAC) state the following,

The responsible person shall complete division-approved corrective action for releases that endanger public health or the environment. The responsible person shall address releases in accordance with a remediation plan submitted to and approved by the division or with an abatement plan submitted in accordance with 19.15.30 NMAC. [emphasis added]

Release characterization is the first phase of corrective action unless the release is ongoing or is of limited volume and all impacts can be immediately addressed. Proper and cost-effective remediation typically cannot occur without adequate characterization of the impacts of any release. Furthermore, the Division has the ability to impose reasonable conditions upon the efforts it oversees. **As such, the Division is requiring a workplan for the characterization of impacts associated with this release be submitted to the OCD District II office in Artesia on or before 4/22/18. If and when the release characterization workplan is approved, there will be an associated deadline for submittal of the resultant investigation report. Modest extensions of time to these deadlines may be granted, but only with acceptable justification.**

The goals of a characterization effort are: 1) determination of the lateral and vertical extents along with the magnitude of soil contamination. 2) determine if groundwater or surface waters have been impacted. 3) If groundwater or surface waters have been impacted, what are the extents and magnitude of that impact. 4) The characterization of any other adverse impacts that may have occurred (examples: impacts on vegetation, impacts on wildlife, air quality, loss of use of property, etc.). To meet these goals as quickly as possible, the following items must, at a minimum, be addressed in the release characterization workplan and subsequent reporting:

- Horizontal delineation of soil impacts in each of the four cardinal compass directions. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. This is not an exclusive list of potential contaminants. Analyzed parameters should be modified based on the nature of the released substance(s). Soil sampling must be both within the impacted area and beyond.
- Vertical delineation of soil impacts. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. As above, this is not an exclusive list of potential contaminants and can be modified. Vertical characterization samples should be taken at depth intervals no greater than five feet apart. Lithologic description of encountered soils must also be provided. At least ten vertical feet of soils with contaminant concentrations at or below these values must be demonstrated as existing above the water table.
- Nominal detection limits for field and laboratory analyses must be provided.
- Composite sampling is not generally allowed.
- Field screening and assessment techniques are acceptable (headspace, titration, EC [include algorithm for validation purposes], EM, etc.), but the sampling and assay procedures must be clearly defined. Copies of field notes are highly desirable. A statistically significant set of split samples must be submitted for confirmatory laboratory analysis, including the laterally farthest and vertically deepest sets of soil samples. Make sure there are at least two soil samples submitted

for laboratory analysis from each borehole or test pit (highest observed contamination and deepest depth investigated). Copies of the actual laboratory results must be provided including chain of custody documentation.

- Probable depth to shallowest protectable groundwater and lateral distance to nearest surface water. If there is an estimate of groundwater depth, the information used to arrive at that estimate must be provided. If there is a reasonable assumption that the depth to protectable water is 50 feet or less, the responsible party should anticipate the need for at least one groundwater monitoring well to be installed in the area of likely maximum contamination.

- If groundwater contamination is encountered, an additional investigation workplan may be required to determine the extents of that contamination. Groundwater and/or surface water samples, if any, must be analyzed by a competent laboratory for volatile organic hydrocarbons (typically Method 8260 full list), total dissolved solids, pH, major anions and cations including chloride and sulfate, dissolved iron, and dissolved manganese. The investigation workplan must provide the groundwater sampling method(s) and sample handling protocols. To the fullest extent possible, aqueous analyses must be undertaken using nominal method detection limits. As with the soil analyses, copies of the actual laboratory results must be provided including chain of custody documentation.

- Accurately scaled and well-drafted site maps must be provided providing the location of borings, test pits, monitoring wells, potentially impacted areas, and significant surface features including roads and site infrastructure that might limit either the release characterization or remedial efforts. Field sketches may be included in subsequent reporting, but should not be considered stand-alone documentation of the site's layout. Digital photographic documentation of the location and fieldwork is recommended, especially if unusual circumstances are encountered.

Nothing herein should be interpreted to preclude emergency response actions or to imply immediate remediation by removal cannot proceed as warranted. Nonetheless, characterization of impacts and confirmation of the effectiveness of remedial efforts must still be provided to the OCD before any release incident will be closed.

Jim Griswold

OCD Environmental Bureau Chief

1220 South St. Francis Drive

Santa Fe, New Mexico 87505

505-476-3465

jim.griswold@state.nm.us

Weaver, Crystal, EMNRD

From: Krakow, Matthew J <Matthew.J.Krakow@andeavor.com>
Sent: Thursday, March 22, 2018 10:54 AM
To: Weaver, Crystal, EMNRD; Bratcher, Mike, EMNRD
Cc: Schneider, Lindsay
Subject: C-141 - Golden Spur 36
Attachments: C-141.pdf

Western Refining Pipeline, LLC is submitting the initial C-141 for the Golden Spur 36 Incident.

Matthew Krakow
Environmental Specialist

111 County Road 4990
Bloomfield, NM 87413
Matthew.J.Krakow@andeavor.com
Office: (505) 632-4169 |
Fax: (505)-632-4021



Please note: My email address changed to Matthew.J.Krakow@andeavor.com on July 31, 2017. Please update your records.

Weaver, Crystal, EMNRD

From: Cordero, Gilbert, EMNRD
Sent: Monday, March 19, 2018 8:23 AM
To: Weaver, Crystal, EMNRD
Cc: Bratcher, Mike, EMNRD
Subject: Fire

Matt Krakow 505-320-3415 with Western Refinery. Chemical Fire at about 10pm 3-17-18. Found evidence at 8:30am 3-18-18. Electrical short possible cause. 32.00242741. 103.7573891. S36 T26S R31E.

Thanks

Sent from my iPhone
Gilbert Cordero Staff Manager
Oil Conservation Division, Artesia
(O) 575-748-1283 114
(C) 575-626-0830