

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

MAR 23 2018

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1808829924

OPERATOR Initial Report Final Report

Name of Company: XTO Energy / *BDP* / *260737* Contact: Kyle Littrell

Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Telephone No. 432-221-7331

Facility Name: Poker Lake Unit 213 Facility Type: Exploration and Production


Surface Owner: Federal Mineral Owner: Federal API No. 30-015-33859

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	18	24S	30E	770	South	550	East	Eddy

Latitude 32.212461 Longitude -103.913943

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 94bbl	Volume Recovered 94bbl
Source of Release Produced water tank	Date and Hour of Occurrence 3/11/2018, AM	Date and Hour of Discovery 3/11/2018, 1:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Crystal Weaver (NMOCD), Jim Amos and Shelly Tucker (BLM)	
By Whom? Jacob Foust	Date and Hour 3/12/2018, 8:31 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* A produced water tank in the impervious lined containment overflowed due to an electrical failure on a transfer pump. Repairs were made to the pump.		
Describe Area Affected and Cleanup Action Taken.* All fluids remained inside the impervious lined containment. A vacuum truck was dispatched and recovered 94 bbl of produced water. An XTO EHS Coordinator who is competent in the operation, maintenance, and inspection of all on-site equipment and facilities visually inspected the containment and verified that there was no visual evidence of a liner breach. All free standing liquids were recovered from the containment and the containment and equipment were power washed.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kyle Littrell	Approved by Environmental Specialist: 	
Title: EHS Coordinator	Approval Date: 3/29/18	Expiration Date: N/A
E-mail Address: Kyle.Littrell@xtoenergy.com	Conditions of Approval:	
Date: 3/23/2018 Phone: 432-221-7331	Attached: <i>2RP-41080</i>	

* Attach Additional Sheets If Necessary


Bratcher, Mike, EMNRD

From: Littrell, Kyle <Kyle_Littrell@xtoenergy.com>
Sent: Friday, March 23, 2018 12:25 PM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; jamos@blm.gov; stucker@blm.gov
Cc: Ruth, Amy; Sanders, Toady; Foust, Bryan; McSpadden, Wes
Subject: Initial/Final C-141 PLU 213 (API 30-015-33859) - XTO Energy
Attachments: Initial-Final C141 PLU 213 3-11-18.pdf



Good Afternoon,

Please find Initial/Final C-141 for the referenced location. Statement and photos are attached per OCD request. Please call with any questions or concerns.


Location sign



Before clean up



After clean up



From: Foust, Bryan
Sent: Monday, March 12, 2018 9:31 AM

To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; jamos@blm.gov; stucker@blm.gov

Cc: Ruth, Amy <Amy_Ruth@xtoenergy.com>; Littrell, Kyle <Kyle_Littrell@xtoenergy.com>; Sanders, Toady <Toady_Sanders@xtoenergy.com>

Subject: Notification of release at PLU 213 battery - XTO Energy

Good morning, I am writing to notify of a produced water release at our Poker Lake Unit 213 battery yesterday afternoon. Total volume of release will be over 25 barrels. Further details will be sent in with C141 once we finish our investigation. Thank you, please don't hesitate to contact me with any questions.

Jake Foust
XTO Energy
432-266-2663

Weaver, Crystal, EMNRD

From: Foust, Bryan <Bryan_Foust@xtoenergy.com>
Sent: Monday, March 12, 2018 8:31 AM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; jamos@blm.gov; stucker@blm.gov
Cc: Ruth, Amy; Littrell, Kyle; Sanders, Toady
Subject: Notification of release at PLU 213 battery - XTO Energy

Good morning, I am writing to notify of a produced water release at our Poker Lake Unit 213 battery yesterday afternoon. Total volume of release will be over 25 barrels. Further details will be sent in with C141 once we finish our investigation. Thank you, please don't hesitate to contact me with any questions.

Jake Foust
XTO Energy
432-266-2663