

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

MAY 30 2018

Form C-141  
Revised April 3, 2017

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.  
**DISTRICT II-ARTESIA O.C.D.**

**Release Notification and Corrective Action**

*NAB1815742127*

**OPERATOR**

Initial Report  Final Report

Name of Company <i>Devon Energy Production Company 6137</i>	Contact <i>Steve McGlassen, Production Foreman</i>
Address <i>6488 Seven Rivers Hwy Artesia, NM 88210</i>	Telephone No. <i>575-748-3371</i>
Facility Name <i>Agate 21 PWU 11H</i>	Facility Type <i>Oil</i>

Surface Owner State	Mineral Owner State	API No. <i>30-015-44200</i>
---------------------	---------------------	-----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>I</i>	<i>20</i>	<i>19S</i>	<i>29E</i>	<i>1420'</i>	<i>FSL</i>	<i>550'</i>	<i>FEL</i>	<i>Eddy</i>

Latitude *32.6429765* Longitude *104.0901813* NAD83

**NATURE OF RELEASE**

Type of Release <i>Natural Gas</i>	Volume of Release <i>289.7 MCF</i>	Volume Recovered <i>0 MCF</i>
Source of Release <i>Relief Valve</i>	Date and Hour of Occurrence <i>May 15, 2018 @ 2:00 PM</i>	Date and Hour of Discovery <i>May 15, 2018 @ 2:00 PM</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <i>N/A</i>	

If a Watercourse was Impacted, Describe Fully.\*  
*N/A*

Describe Cause of Problem and Remedial Action Taken.\*  
*Relief valve on buy back gas line popped off causing gas release. The well was shut in to stop the release and repairs have been made.*

Describe Area Affected and Cleanup Action Taken.\*  
*Approximately 289.7 MCF was released.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dana DeLaRosa</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <i>Dana DeLaRosa</i>		Approved by Environmental Specialist <i>[Signature]</i>	
Title: <i>Field Admin Support</i>		Approval Date: <i>6/15/18</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>Dana.Delarosa@dvn.com</i>		Conditions of Approval:	
Date: <i>5/30/2018</i> Phone: <i>575.746.5594</i>		<i>FINAL</i>	
		Attached <input type="checkbox"/> <i>289.4774</i>	

\* Attach Additional Sheets If Necessary

**Bratcher, Mike, EMNRD**

---

**From:** DeLaRosa, Dana <Dana.DeLaRosa@divn.com>  
**Sent:** Wednesday, May 30, 2018 9:06 AM  
**To:** Weaver, Crystal, EMNRD; Bratcher, Mike, EMNRD  
**Cc:** Fulks, Brett; Shoemaker, Mike  
**Subject:** Agate 21 PWU 11H\_289.7MCF\_5.16.2018  
**Attachments:** Agate 21 PWU 11H\_289.7MCF\_5.16.2018\_Intial Final C141.doc; Agate 21 PWU 11H\_289.7mcf\_5.16.2018\_GIS Image.pdf

Good Morning,

Attached you will find a C141 and a GIS Image for the 289.7MCF air release that occurred at the Agate 21 PWU 11H on 5.16.2018. The red dot on the GIS Image represents the approximate origin of release.

Thank you,

*Dana DeLaRosa*

Field Admin Support  
Production  
A-Schedule

Devon Energy Corporation  
PO Box 250  
Artesia, NM 88211  
575 746 5594



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.

Agate 21 PWU 11H

289.7mcf\_5.16.2018

  
devon

This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS\_1984\_Web\_Mercator\_Auxiliary\_Sphere  
Prepared by: Dana DeLaRosa  
Map is current as of: 23-May-2018



Miles  
0 0.00 0.01 0.02 1:889

S20, T19S, R29E

289.7mcf