

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAY 31 2018

Form C-141
Revised April 3, 2017

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.
DISTRICT II-ARTESIA O.C.D.

Release Notification and Corrective Action

NAB 815841229

OPERATOR

Initial Report Final Report

Name of Company <i>Devon Energy Production Company 0137</i>	Contact Wes Ryan, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-748-3371
Facility Name Cotton Draw Unit 167H (release occurred at the Cotton Draw Unit 25 CTB 1)	Facility Type Oil
Surface Owner Federal	Mineral Owner Federal
API No. 30-015-41385	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	25	24S	31E					Eddy

Latitude 32.187567 Longitude 103.731529 NAD83

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 13.286bbbls	Volume Recovered 13.286bbbls
Source of Release Produced water tank	Date and Hour of Occurrence May 17, 2018 @ 10:27 AM MST	Date and Hour of Discovery May 17, 2018 @ 10:27 AM MST
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

The circulating pumps went down causing produced water to fill the tanks and then overflow. The tanks were immediately equalized and the pump was reset to stop any further release from occurring.

Describe Area Affected and Cleanup Action Taken.*

Approximately 13.286bbbls of produced water was released into the lined SPCC containment ring. A vacuum truck was dispatched and recovered approximately 13.268 bbbls of produced water from the lined containment. All fluid stayed inside the lined SPCC containment. Once fluids were removed the liner was visually inspected by Devon field staff for any pinholes or punctures and none were found. Based on this inspection there is no evidence that the spill fluids left containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>		OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher		Approved by Environmental Specialist <i>[Signature]</i>	
Title: Field Admin Support		Approval Date: <i>4/15/18</i>	Expiration Date: <i>N/A</i>
E-mail Address: Sheila.Fisher@dvn.com		Conditions of Approval: <i>FINAL</i>	
Date: 5/21/18	Phone: 575.748.1829	Attached <input checked="" type="checkbox"/> <i>JRP 4783</i>	

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Fisher, Sheila <Sheila.Fisher@dvn.com>
Sent: Thursday, May 31, 2018 2:37 PM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Shelly Tucker (stucker@blm.gov)
Cc: Shoemaker, Mike; Fulks, Brett; Ryan, Wesley; Linam, Harry
Subject: Cotton Draw Unit 25 CTB 1 closest location(Cotton Draw Unit 167H)_13.286bbbls pw_5.17.18
Attachments: Cotton Draw Unit 25 CTB 1 closest location(Cotton Draw Unit 167H)_13.286bbbls pw_Initial & Final C-141_5.17.18.doc; Cotton Draw Unit 25 CTB 1 closest location(Cotton Draw Unit 167H)_13.286bbbls pw_GIS Image_5.17.18.pdf

Good Afternoon,

Attached please find the Initial & Final C-141 and GIS Image for the 13.286bbbls produced water release at the Cotton Draw Unit 25 CTB 1 closest location is Cotton Draw Unit 167H on 5.17.18.

If you have any questions please feel free to contact us.

Thank you,

Sheila Fisher
Field Admin Support
Production
B-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.

Cotton Draw Unit 167H (release occurred at the Cotton Draw 25 CTB 1)

13.286bbls pw_5.17.18



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by: Sheila Fisher
Map is current as of: 31-May-2018



Miles
0 0.01 0.02 0.04 1:1,779

