

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JUN 18 2018

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

DISTRICT OFFICE TO APPROPRIATE DISTRICT OFFICE IN ACCORDANCE WITH 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1817241489

OPERATOR X Initial Report X Final Report

Name of Company Vanguard Operating, LLC <i>258350</i>	Contact Jason Fisher
Address 5847 San Felipe, Ste. 3000 Houston, TX 77057	Telephone No. 505-918-0523
Facility Name Staley State A Battery Staley State #25 Well	Facility Type Central Battery and Well Site
Surface Owner	Mineral Owner State
API No. 30-015-41066	

LOCATION OF RELEASE



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	30	17S	28E	2310	South	965	East	Eddy

Latitude 32.8041649 Longitude -104.2095261 NAD83

NATURE OF RELEASE

Type of Release Gas	Volume of Release 472 mcf	Volume Recovered 0
Source of Release Flare	Date and Hour of Occurrence 6-12-2018	Date and Hour of Discovery 6-12-2018
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Gas purchaser requested curtailment of gas due to compressor problems on their residue line. The gas was sent to flare for 18 hours.		
Describe Area Affected and Cleanup Action Taken.*		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:  Printed Name: Chuck Johnston Title: EHS Specialist E-mail Address: cjohnston@vnrenergy.com Date: 6-18-2018 Phone: 432-202-4771	<p>OIL CONSERVATION DIVISION</p> Signed By  Approved by Environmental Specialist: Approval Date: <u>6/19/18</u> Expiration Date: <u>N/A</u> Conditions of Approval: FINAL Attached: APP 4820
--	--

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Chuck Johnston <cjohnston@vnrenergy.com>
Sent: Monday, June 18, 2018 9:31 AM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD
Subject: Flare
Attachments: Staley State and Staley State A Batteries Flare.pdf

Mike and Crystal, please find attached the Initial/Final C-141 for the Staley State and Staley State A batteries. The gas purchaser requested a curtailment due to compressor problems on their residue line. We flared 18 hours total from 6-12-18.

Thanks,

Chuck Johnston
EHS / Operations Specialist
432-202-4771 Cell
432-248-8154 Office

