

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources JUN 25 2018

Form C-141
Revised April 3, 2017

Oil Conservation Division Submit 1 Copy to appropriate District Office in
1220 South St. Francis Dr. DISTRICT II-ARTESIA O.C.D. in accordance with 19.15.29 NMAC.
Santa Fe, NM 87505

Release Notification and Corrective Action

NAB1817954837

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production Company <i>10137</i>	Contact Wesley Ryan, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-748-3371
Facility Name Snapping 2 State 7H	Facility Type Oil

Surface Owner State	Mineral Owner State	API No. 30-015-39163
---------------------	---------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	2	26S	31E					Eddy

Latitude_32.066033_ Longitude_103.748488_ NAD83

NATURE OF RELEASE

Type of Release Oil	Volume of Release 28bbls oil	Volume Recovered 28bbls oil
Source of Release Hole in oil tank	Date and Hour of Occurrence June 11, 2018 @ 11:00 AM MST	Date and Hour of Discovery June 11, 2018 @ 11:00 AM MST
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD-Mike Bratcher & Crystal Weaver NMSLO-Ryan Mann	
By Whom? Mike Shoemaker, EHS Professional	Date and Hour June 12, 2018 @ 8:07 AM MST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Oil tank developed a hole in the bottom and released oil into the lined SPCC containment ring. A vacuum truck was dispatched to recover fluids from the lined containment.

Describe Area Affected and Cleanup Action Taken.*

Approximately 28 bbls of oil was released into the lined SPCC containment ring. A vacuum truck was dispatched and recovered approximately 28 bbls of oil from lined containment. All fluid stayed inside the lined SPCC containment. Once fluids were removed the liner was visually inspected by Devon field staff for any pinholes or punctures and none were found. Based on this inspection there is no evidence that the spill fluids left containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Dana DeLaRosa</i>	Approved by Environmental Specialist Signed By <i>[Signature]</i>	
Printed Name: Dana DeLaRosa	Approval Date: <i>6/26/18</i>	Expiration Date: <i>N/A</i>
Title: Field Admin Support	Conditions of Approval: FINAL	
E-mail Address: Dana.Delarosa@dvn.com	Attached <i>AR 4830</i>	
Date: _____ Phone: 575.746.5594		

* Attach Additional Sheets If Necessary

Snapping 2 State 7H

28BBL5 Oil_6.11.2018



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by: Dana DeLaRosa
Map is current as of: 14-Jun-2018



Miles
0 0.00 0.01 0.02 1:889



Bratcher, Mike, EMNRD

From: DeLaRosa, Dana <Dana.DeLaRosa@dvn.com>
Sent: Monday, June 25, 2018 10:59 AM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; rmann@slo.state.nm.us
Cc: Shoemaker, Mike; Fulks, Brett
Subject: Snapping 2 State 7H_28BBLs Oil_6.11.2018
Attachments: Snapping 2 St 7H_6.11.2018_2018_Intial C141.doc; Snapping 2 State 7H_28BBLs Oil_6.11.2018_GIS Image.pdf

Good Morning,

Attached you will find the C141 and GIS Image for the 28bbl oil release that occurred on 6.11.2018 at the Snapping 2 State 7H. The red dot on the GIS image represents the approximate origin of release.

If you have any questions, feel free to contact me.

Thank you,

Dana DeLaRosa

Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 746 5594



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.

Bratcher, Mike, EMNRD

From: Shoemaker, Mike <Mike.Shoemaker@dvn.com>
Sent: Tuesday, June 12, 2018 8:07 AM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Mann, Ryan
Cc: Fulks, Brett
Subject: Snapping 2 State 7H (API #30-015-39163)

Devon had the following release occur at 11:00 AM MST on 06/11/18. The incident is described below.

1. Snapping 2 State 7H (API #30-015-39163)
 - a. Oil tank developed a hole in the bottom and released oil into the lined SPCC containment ring. Approximately 28 bbls of produced water was released into the lined containment. Approximately 28 bbls were recovered.

A C-141 will be prepared and submitted with GPS coordinates of the area affected.

Thanks,

Mike Shoemaker
EHS Representative

Devon Energy Corporation
6488 Seven Rivers Highway
Artesia, New Mexico 88210
575-746-5566 Office
575-513-5035 Mobile



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.