

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

JUL 09 2018

Form C-141  
Revised April 3, 2017

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
DISTRICT II-ARTESIA, NM 88210 with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*NAB1819449392*

**OPERATOR**

Initial Report  Final Report

Name of Company: XTO Energy <i>2100737</i>	Contact: Kyle Littrell
Address: 3104 E. Greene St., Carlsbad, N.M. 88220	Telephone No: 432-221-7331
Facility Name: JRU DI 1A Tank Battery (API 203H JRU DI 1A)	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No: 30-015-43237
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	21	22S	30E	2033	North	2595	West	Eddy

Latitude 32.379351° Longitude -103.88655° NAD83



**NATURE OF RELEASE**

Type of Release	Crude Oil	Volume of Release	135 bbls	Volume Recovered	135 bbls
Source of Release	Tank Overflow	Date and Hour of Occurrence	6/25/2018 time unknown	Date and Hour of Discovery	6/25/2018 6:47 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher/Crystal Weaver (NMOCD), Shelly Tucker/Jim Amos (BLM)		
By Whom?	Amy Ruth	Date and Hour:	6/25/2018 at 9:03 am by email		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		
If a Watercourse was Impacted, Describe Fully.*	N/A				

Describe Cause of Problem and Remedial Action Taken.\*  
The LACT unit had shut in on bad oil due to a wiring problem. As two tanks filled and overflowed, an alarm was not distributed due to a recent SCADA reconfiguration that had disabled the alarm. A contract flow back employee discovered the overflowing tanks and provided notification. The alarming system is being corrected to ensure notifications will be distributed.

Describe Area Affected and Cleanup Action Taken.\*  
The release affected the newly constructed lined tank battery containment. No fill material was located inside containment. A XTO SH&E Coordinator who is competent in the operation, maintenance, and inspection of all on-site equipment and facilities visually inspected the containment and verified that there was no visual evidence of a liner breach. All free-standing fluids were recovered from the containment and equipment was power washed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amy C. Ruth	Signed By:  Approved by Environmental Specialist:	
Title: Environmental Coordinator	Approval Date: <i>7/11/18</i>	Expiration Date: <i>N/A</i>
E-mail Address: Amy_Ruth@xtoenergy.com	Conditions of Approval: <b>FINAL</b>	
Date: 7/9/2018 Phone: 575-689-3380	Attached: <input checked="" type="checkbox"/> <i>APP-4853</i>	

\* Attach Additional Sheets If Necessary

## Bratcher, Mike, EMNRD

---

**From:** Ruth, Amy <Amy\_Ruth@xtoenergy.com>  
**Sent:** Monday, July 9, 2018 1:08 PM  
**To:** Bratcher, Mike, EMNRD; Tucker, Shelly; jamos@blm.gov  
**Cc:** McSpadden, Wes; Sanders, Toady; Littrell, Kyle; Foust, Bryan  
**Subject:** Initial/Final C-141 - James Ranch Unit DI#1A Battery (API 203H JRU DI 1A 30-015-43237)  
**Attachments:** Initial-Final C-141 JRU DI 1A 6-25-18.pdf

Good Afternoon,

Attached is an initial/final C-141 for the referenced release event. Below are photos of the initial release followed by photos of the cleaned facility. Please call with any questions or concerns and have a good afternoon. Many thanks.



This document may contain information that is privileged, confidential and exempt from disclosure under applicable law. If you are not the intended recipient, you are notified that any unauthorized disclosure, copying, distribution or action on/of the contents of this document is prohibited.

**From:** Ruth, Amy

**Sent:** Monday, June 25, 2018 9:03 AM

**To:** Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Tucker, Shelly; jamos@blm.gov

**Cc:** McSpadden, Wes; Sanders, Toady; Littrell, Kyle; Foust, Bryan

**Subject:** Release Notification - James Ranch Unit DI#1A Battery (GPS: 32.379358N, -103.886721W)

Good morning,

This is sent as notification of a release of fluids in excess of 25 barrels from the referenced facility discovered this morning. Details will be provided with an initial C-141 submittal. Please call us with questions or concerns. Thank you.

Respectfully,

*Amy C. Ruth*

Delaware Basin Division

Environmental Coordinator

3104 E. Greene Street | Carlsbad, NM 88220 | M: 432.661.0571 | O: 575.689.3380



This document may contain information that is privileged, confidential and exempt from disclosure under applicable law. If you are not the intended recipient, you are notified that any unauthorized disclosure, copying, distribution or action on/of the contents of this document is prohibited.