

8:30 8:30 8:30 6:00 31:30

State of New Mexico  
Energy Minerals and Natural Resources

JUL 19 2018

Form C-141  
Revised April 3, 2017

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

DISTRICT II ARTESIA O.C.D.  
Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**PAB1820643005**

**Release Notification and Corrective Action**

**OPERATOR**

**NAB1820657601**

Initial Report  Final Report

Name of Company EOG Y Resources, Inc.	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 <sup>th</sup> Street Artesia NM 88210	Telephone No. 575-748-1471	
Facility Name Bones Bad Transfer Station	Facility Type Transfer Station	

Surface Owner Fee	Mineral Owner Fee	API No.
----------------------	----------------------	---------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	31	18S	26E					Eddy

Latitude 32.73575 Longitude -104.50961 NAD83

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 22 B/PW	Volume Recovered 22 B/PW
Source of Release 2" Steel line	Date and Hour of Occurrence 07/03/2018; 9:30 AM	Date and Hour of Discovery 07/03/2018; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\* N/A

Describe Cause of Problem and Remedial Action Taken.\*  
2" steel suction line on transfer pump leaked.

Describe Area Affected and Cleanup Action Taken.\*

The impacted area is approximately 30' X 30' within lined and bermed containment SE of the Bones BAD Com #1 Battery. Vacuum truck and roustabout crews were called. All (100%) of the produced water has been recovered and gravel removed and the affected liner exposed, the NMOCD was notified on 7/16/2018 that EOG will inspect the liner, the liner was inspected (7/18/2018) and the liner remains intact. **Based off of information within the Form C-141 and attached documentation, EOG Resources, Inc. requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Robert Asher	Approved by Environmental Specialist: 		
Title: Safety & Environmental Supervisor	Approval Date: 7/20/18	Expiration Date: N/A	
E-mail Address: bob_asher@eogresources.com	Conditions of Approval: <b>FINAL</b>		Attached: <b>REP-4867</b>
Date: July 19, 2018	Phone: 575-748-4217		

\* Attach Additional Sheets If Necessary

## Bratcher, Mike, EMNRD

---

**From:** Bob Asher <Bob\_Asher@eogresources.com>  
**Sent:** Thursday, July 19, 2018 2:14 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Yvette Moore; Chase Settle; Katie Jamison  
**Subject:** Revised Form C-141, Initial/Final Report (Bones BAD Transfer Station)  
**Attachments:** Revised Form C-141, Initial & Final Report (Bones BAD Transfer Station, ....pdf

Mike,

Attached is the revised Form C-141, Initial/Final report per our telephone conversation this afternoon.

Thank you,

**Robert C. "Bob" Asher**  
**Environmental Supervisor**  
Safety & Environmental Department  
EOG Resources, Inc.  
Artesia Division  
EOG Safety Begins With YOUR Safety



---

**From:** Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]  
**Sent:** Thursday, July 19, 2018 9:33 AM  
**To:** Bob Asher <Bob\_Asher@eogresources.com>  
**Cc:** Yvette Moore <Yvette\_Moore@eogresources.com>; Chase Settle <Chase\_Settle@eogresources.com>; Katie Jamison <Katie\_Jamison@eogresources.com>; Pruett, Maria, EMNRD <Maria.Pruett@state.nm.us>  
**Subject:** RE: Form C-141, Initial/Final Report (Bones BAD Transfer Station)

**CAUTION:** This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Good Morning Bob,

Just wanted to bring to your attention a couple of issues with this submittal. The new Part 29 rule is not in effect yet. I think the format of your submittal is probably very sufficient to meet most of the requirements of the rule once it is in effect. The portion of the new rule that you referenced, specifically the second one mentioned, you have listed as 19.15.29.22 (5)(i). I believe what you meant to reference is actually 19.15.29.11 (5)(a)(i). Also, a relevant portion of the proposed new rule would be, 19.15.29 (5)(a)(ii), which requires "...at least two business days' notice to the appropriate division district office before conducting the liner inspection." You may have provided that notification, but if not, that will also be required under the proposed rule (even though typical staffing levels rarely allow us to witness these events). At this time, if you want to submit the C-141 referencing the proposed rule, I can accept it for record and enter the data. It would show as a closed incident, even though being "accepted for record". Let me know if you want to modify it or process it as sent.

Thank you,

Mike Bratcher

NMOCD District 2  
811 South First Street  
Artesia, NM 88210  
575-748-1283 Ext 108

---

**From:** Bob Asher <[Bob\\_Asher@eogresources.com](mailto:Bob_Asher@eogresources.com)>  
**Sent:** Wednesday, July 18, 2018 4:13 PM  
**To:** Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>  
**Cc:** Yvette Moore <[Yvette\\_Moore@eogresources.com](mailto:Yvette_Moore@eogresources.com)>; Chase Settle <[Chase\\_Settle@eogresources.com](mailto:Chase_Settle@eogresources.com)>; Katie Jamison <[Katie\\_Jamison@eogresources.com](mailto:Katie_Jamison@eogresources.com)>  
**Subject:** Form C-141, Initial/Final Report (Bones BAD Transfer Station)

Thank you,

**Robert C. "Bob" Asher**  
**Environmental Supervisor**  
Safety & Environmental Department  
EOG Resources, Inc.  
Artesia Division  
Artesia, NM 88210  
575-748-4217 (Office)  
575-365-4021 (Cell)  
**EOG Safety Begins With YOUR Safety**

