

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JUL 20 2018

Form C-141
Revised April 3, 2017

Oil Conservation Division DISTRICT IV ARTESIA O.C.D. Appropriate District Office in accordance with 19.15.29 NMAC.
1220 South St. Francis Dr.
Santa Fe, NM 87505

Release Notification and Corrective Action

NAB1820743403
OPERATOR Initial Report Final Report
 Name of Company: XTO Energy *BOPCO 2100737* Contact: Kyle Littrell
 Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Telephone No: 432-221-7331
 Facility Name: Poker Lake Unit 428 Battery Facility Type: Exploration and Production
 Surface Owner: Federal Mineral Owner: Federal API No: 30-015-41246

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	34	24S	30E	850	North	2225	West	Eddy

Latitude 32.179630 Longitude -103.871155 NAD83

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 147bbl	Volume Recovered 147bbl
Source of Release Transfer pump	Date and Hour of Occurrence 7/7/2018, AM	Date and Hour of Discovery 7/7/2018, 12:45 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Crystal Weaver (NMOCD), Jim Amos and Shelly Tucker (BLM)	
By Whom? Kyle Littrell	Date and Hour: 7/9/2018, 7:47 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* A nipple on a water transfer pump broke, likely due to vibration and corrosion, releasing produced water into impervious lined containment. Pump was shut in and repairs were made.		
Describe Area Affected and Cleanup Action Taken.* All fluid was captured within the impervious lined containment, with no impact to the soil. Vacuum trucks were dispatched and recovered all fluids. A XTO SH&E coordinator who is competent in the operation, maintenance, and inspection of all on-site equipment and facilities visually inspected the containment and verified that there was no visual evidence of a liner breach. Containment was pressure washed and facility returned to production.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature:	OIL CONSERVATION DIVISION	
Printed Name: Kyle Littrell	Signed By: Approved by Environmental Specialist:	
Title: Environmental Coordinator	Approval Date: 7/20/18	Expiration Date: N/A
E-mail Address: Kyle.Littrell@xtoenergy.com	Conditions of Approval: FINAL	
Date: 7/20/2018 Phone: 432-221-7331	Attached:	

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Littrell, Kyle <Kyle_Littrell@xtoenergy.com>
Sent: Monday, July 9, 2018 7:47 AM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Jim Amos; Tucker, Shelly (stucker@blm.gov)
Cc: Sanders, Toady; McSpadden, Wes; Ruth, Amy; Foust, Bryan
Subject: Release Notification - PLU 428 Battery (API# 30-015-41246 for PLU 428)

Good Morning,

This is sent as notification of a release of fluids in excess of 25 barrels from the referenced facility. Release was fully contained within impervious secondary containment. Details will be provided with the initial C-141 submittal. Please contact me with any questions or concerns. Thanks. --Kyle

Kyle Littrell
SH&E Coordinator
XTO Energy Inc.
Delaware Division
Phone:(432)-221-7331 | Mobile:(970)-317-1867
kyle_littrell@xtoenergy.com

An **ExxonMobil** Subsidiary