

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JUN 28 2018

Form C-141
Revised April 3, 2017

Oil Conservation Division DISTRICT IV ARTESIA, NM
1220 South St. Francis Dr. Appropriate District Office in accordance with 19.15.29 NMAC.
Santa Fe, NM 87505

Release Notification and Corrective Action

DAB18212374510

372338

OPERATOR

Initial Report Final Report

Name of Company NGL Water Solutions Permian LLC	Contact
Address 1509 W Wall Street, Ste 306, Midland, TX 79701	Telephone No.
Facility Name Striker 3 SWD	Facility Type Salt Water Disposal Facility

Surface Owner NGL	Mineral Owner NA	API No. 30-015-44407
-------------------	------------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 33	Township 23S	Range 28E	Feet from the 472	North/South Line South	Feet from the 897	East/West Line East	County Eddy
---------------	------------	--------------	-----------	-------------------	------------------------	-------------------	---------------------	-------------

Latitude 32.255078 Longitude -104.086499 NAD83

NATURE OF RELEASE *10 bbls Oil / 222 bbls Water*

Type of Release Oil and Produced Water	Volume of Release <i>232 bbls</i>	Volume Recovered
Source of Release Tank Overflow in containment	Date and Hour of Occurrence 9AM on 6/27/2018	Date and Hour of Discovery 9AM on 6/27/18
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Sarah Jordan	Date and Hour 6/28/18 @ 930AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES. Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*
Employee did not perform proper hourly checks and tank overflowed 10 bbls oil and 222 bbls of water into a cement containment. All fluids remained in containment.

Describe Area Affected and Cleanup Action Taken.*
Cement Containment

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sarah Jordan</i>	OIL CONSERVATION DIVISION	
Printed Name: Sarah Jordan	Approved by Environmental Specialist <i>[Signature]</i>	
Title: Manager of Regulatory Compliance	Approval Date: <i>7/30/18</i>	Expiration Date: <i>N/A</i>
E-mail Address: sarah.jordan@nglep.com	Conditions of Approval: <i>See attached</i>	Attached <input type="checkbox"/> <i>2RD-4883</i>
Date: _____ Phone: 432/685-0005 x1989		

* Attach Additional Sheets If Necessary

*LATE ENTRY
MLB/OD*

Bratcher, Mike, EMNRD

From: Sarah Jordan <Sarah.Jordan@nglep.com>
Sent: Thursday, June 28, 2018 8:55 AM
To: Bratcher, Mike, EMNRD
Cc: Sarah Jordan
Subject: Striker 3 SWD Spill
Attachments: scanner@nglep.com_20180628_090626.pdf

I will sent the final report when cleanup is complete. Please let me know If you need anything else.

Thank you,

Sarah Jordan
Regulatory Compliance Manager
NGL Water Solutions- Permian/ Eagleford and Choya Operating, LLC
432/685-0005 x 1989
Sarah.jordan@nglep.com

-----Original Message-----

From: scanner@nglep.com [mailto:scanner@nglep.com] On Behalf Of scanner@
Sent: Thursday, June 28, 2018 9:06 AM
To: Sarah Jordan
Subject: Scanned image from MX-5141N

Reply to: scanner@nglep.com <scanner@nglep.com> Device Name: TxSharp_1 Device Model: MX-5141N
Location: Wall_Street

File Format: PDF (Medium)
Resolution: 300dpi x 300dpi

Attached file is scanned image in PDF format.

Use Acrobat(R)Reader(R) or Adobe(R)Reader(R) of Adobe Systems Incorporated to view the document.

Adobe(R)Reader(R) can be downloaded from the following URL:

Adobe, the Adobe logo, Acrobat, the Adobe PDF logo, and Reader are registered trademarks or trademarks of Adobe Systems Incorporated in the United States and other countries.

<http://www.adobe.com/>