


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Name of Company Chevron U.S.A. INC	Contact Danny Lovell
Address P.O. Box 1949 Eunice NM 88231	Telephone No. 505-394-1242
Facility Name A.H. Blinebry Fed NCT #2 BTY	Facility Type- Production

Initial Report Final Report

Surface Owner D.K. Boyd	Mineral Owner-Federal	Lease No.
-------------------------	-----------------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	29	22s	38e					Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release 30 BO/3BW	Volume Recovered 3 BO
Source of Release- Circulating pump.	Date and Hour of Occurrence 10/21/05	Date and Hour of Discovery 10/21/05 10:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Sylvia Dickey	
By Whom? Larry Williams	Date and Hour 10/21/05 3:05 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* 1/2" nipple on circulating pump broke off in threads due to excessive vibration. Pump was taken out of service.

Describe Area Affected and Cleanup Action Taken.* Affected approx 542 sq/ft of pasture land. Area was fenced off and landowner notified. D.K Boyd stated he would get with Chevron on remediation of area. Depth to ground water=174'

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Danny Lovell	Approved by District Supervisor:	
Title: Operations Rep	Approval Date:	Expiration Date:
E-mail Address: LOVD@chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/25/05 Phone: 394-1242		

* Attach Additional Sheets If Necessary

Facility - PAC06B753583
Incident - PAC06B753668
application - PAC06B753964