

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company CHEVRONTEXACO	Contact Danny Lovell
Address P.O. Box 1949 Eunice NM. 88231	Telephone No. 505-394-1242 (office), 505-390-0866 (cell)
Facility Name- CDU BTY #19	Facility Type - Production

Surface Owner- Tom Kennan	Mineral Owner - State of New Mexico	Lease No.
---------------------------	-------------------------------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	29	21S	37E					Lea

Latitude 32 26.712N Longitude 103 10.654W

NATURE OF RELEASE

Type of Release-Oil & Produced Water	Volume of Release 60BO & 380BW	Volume Recovered- 58BO & 350BW
Source of Release- 1000 BBL Steel Tank	Date and Hour of Occurrence- 5/31/06	Date and Hour of Discovery 5/31/06 @ 6:45 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton	
By Whom? Danny Lovell	Date and Hour 5/31/06 @ 3:30 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Transfer pump went down due to electrical storm from previous night allowing tank to fill up to 10' where a hole developed allowing fluid to be released. Reset transfer pump and equalized from bottom into empty tank. Tank removed from service.

Describe Area Affected and Cleanup Action Taken.* All fluid was contained within a lined berm. Oil was skimmed off with vacuum truck and put in stock tank and remaining water vacuumed up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Larry Williams</i>	OIL CONSERVATION DIVISION	
Printed Name: Larry Williams	Approved by District Supervisor: <i>Paul Blaney</i>	
Title: HES Champion	Approval Date: <i>6-12-06</i>	ENVIRONMENTAL ENGINEER Expiration Date:
E-mail Address: lcwl@chevrontexaco.com	Conditions of Approval:	
Date: 6/5/06 Phone: 505-394-1237	<i>Delaware CI, BTEX, TPH</i>	



* Attach Additional Sheets If Necessary
Facility - FPAC 0616539728
Incident - NPAC 0616539839
Application - FPAC 0616540063