

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company <u>Chevron USA Inc.</u>	Contact <u>Wayne Minchew</u>
Address <u>HCR 60 Box 423 Lovington, NM 88260</u>	Telephone No. <u>505-396-4414</u>
Facility Name <u>West Lovington Unit #56</u>	Facility Type <u>Injection Well</u>
Surface Owner <u>Darr Angel</u>	Mineral Owner <u>State of NM</u> Lease No. <u>B-4704</u>

AP #30025039110000 **LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Fcct from the	North/South Line	Fcct from the	East/West Line	County
G	8	17S	36E	1980	North	1980	East	Lea

Latitude Longitude

**NATURE OF RELEASE**

Type of Release <u>Produced Water</u>	Volume of Release <u>25 bbls</u>	Volume Recovered. <u>20 bbls</u>
Source of Release <u>Injection Line</u>	Date and Hour of Occurrence <u>04-26-06 1230</u>	Date and Hour of Discovery <u>04-26-06 1230</u>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>Pat Caperton</u>	
By Whom? <u>Larry Ridenour</u>	Date and Hour <u>04-26-06 1400</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*


Internal and External corrosion. 1" plastic coated steel riser split. Well shut in.

Describe Area Affected and Cleanup Action Taken.\*

Pasture and mesquite, water stayed on location. Vacuum truck picked up standing water.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>P.W. Minchew</u>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <u>Wayne Minchew</u>	Approved by District Supervisor:	
Title: <u>Operations Supervisor</u>	Approval Date:	Expiration Date:
E-mail Address: <u>pminchew@chevron.com</u>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>Phone: 505-396-4414</u>		



\* Attach Additional Sheets If Necessary

incident - PAC061734887  
application - PAC0617349054

RPT#930