

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company ConocoPhillips	Contact Stephen Wilson
Address HC60 Box 66, Lovington, NM	Telephone No. 505-390-3106
Facility Name Vacuum ABO Battery #3	Facility Type Oil and Gas

Surface Owner State of NM	Mineral Owner	Lease No 30-025-03007-00-00
----------------------------------	---------------	------------------------------------

LOCATION OF RELEASE

Unit Letter L	Section 34	Township 17s	Range 35E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea, NM
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	--------------------------

Latitude N 32° 47.270' Longitude W 103° 27.023'

NATURE OF RELEASE

Type of Release produced water	Volume of Release 15bbl (0oil, 15water)	Volume Recovered (0oil, 13water)
Source of Release 2" produced water injection line	Date and Hour of Occurrence 06-13-06 10:00am	Date and Hour of Discovery 06-13-06 10:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

30 miles West of Hobbs NM, North of ConocoPhillips ABO Battery 3. During new construction operations, a track hoe was digging a trench in preparation to install a 6" fiberglass line when the track hoe bucket contacted and cracked a 2" WIW line. One Call System had been notified and protocol followed. The line was isolated and will remain SI until construction in that area is complete. 12 bbls of produced water was recovered. The weather was clear and hot with no cattle present.

Describe Area Affected and Cleanup Action Taken.*

Discharge sprayed 60" x 60' x 1" pasture and pooled in a 30' x 30' x 3" of pasture. Vacuum truck out to pick up free liquids. A determination will be made as to the need for any further action. If further action is deemed necessary a follow up report will be filed. No cattle in the area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.



Signature:	OIL CONSERVATION DIVISION	
Printed Name: Stephen R. Wilson	Approved by District Supervisor:	
Title: Sr. SHEAR Specialist	Approval Date:	Expiration Date:
E-mail Address: Stephen.R.Wilson@ConocoPhillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06-21-06 Phone: 505-390-3106		

* Attach Additional Sheets If Necessary

incident - n PAC0618728695

application - PAC0618728695

RP# 944