

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Range Operating New Mexico, Inc.	Contact	Linda C. Stiles
Address	777 Main Street Suite 800 Fort Worth TX 76102	Telephone No.	(817) 810-1908
Facility Name	Simmons #2	Facility Type	SWD

Surface Owner	Wayne Henson	Mineral Owner	See Attached	Lease No.	301553
---------------	--------------	---------------	--------------	-----------	--------

LOCATION OF RELEASE

AP1 #30025 22039 0000

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	5	22S	37E	2310	North	1980	East	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	130	Volume Recovered	120
Source of		Date and Hour of Occurrence	5-24-06	Date and Hour of Discovery	7:00 AM 5-24-06
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	E. L. Gonzales		
By Whom?	Steve Almager	Date and Hour	7:15 AM 5-24-06		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	NA		

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*
Disposal pump went down on electrical. Answering service received alarm but did not call Range Representative
Recovered the majority of fluid on ground and let dry, come back in the morning and scrap off the top of the spill area and haul to Sundance Disposal, then replace the area with clean caliche.

Describe Area Affected and Cleanup Action Taken.*
Area Affected is on the Simmons #2 SWD Pad between guidewires.
Scrap off the top of the spill area and haul to Sundance Disposal, then replace the area with clean caliche.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Linda C. Stiles		Approved by District Supervisor:	
Title: Sr. Engineering Tech		Approval Date:	Expiration Date:
E-mail Address: lstyles@rangeresources.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5-25-06	Phone: (817) 810-1908		

* Attach Additional Sheets If Necessary

incident - n PACO 620934752
application - p PACO 620935013

RP#980

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report x Final Report

Name of Company	Range Operating New Mexico, Inc.	Contact	Linda C. Stiles
Address	777 Main Street Suite 800 Fort Worth TX 76102	Telephone No.	(817) 810-1908
Facility Name	Simmons #2	Facility Type	SWD

Surface Owner	Wayne Henson	Mineral Owner	See Attached	Lease No.	301553
---------------	--------------	---------------	--------------	-----------	--------

LOCATION OF RELEASE

30025 220390000

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	5	22S	37E	2310	North	1980	East	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	130	Volume Recovered	120
Source of		Date and Hour of Occurrence	5-24-06	Date and Hour of Discovery	7:00 AM 5-24-06

Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	E. L. Gonzales
-----------------------------	-----------------------------------------------------------------------------------------------------------	------------------	----------------

By Whom?	Steve Almager	Date and Hour	7:15 AM 5-24-06
----------	---------------	---------------	-----------------

Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	NA
----------------------------	---------------------------------------------------------------------	-------------------------------------------	----

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*
Disposal pump went down on electrical. Answering service received alarm but did not call Range Representative
Recovered the majority of fluid on ground and let dry, came back in the morning and scraped off the top of the spill area and hauled to Sundance Disposal, then replaced the area with clean caliche.

Describe Area Affected and Cleanup Action Taken.*
Area Affected is on the Simmons #2 SWD Pad between guidewires.

Scraped off the top of the spill area and hauled to Sundance Disposal, then replaced the area with clean caliche.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION 		
Printed Name: Linda C. Stiles	Approved by District Supervisor:		
Title: Sr. Engineering Tech	Approval Date:		Expiration Date:
E-mail Address: lstiles@rangeresources.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 5-25-06 Phone: (817) 810-1908			

* Attach Additional Sheets If Necessary