

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company ConocoPhillips Company	Contact Kenneth N. Andersen
Address 4001 Penbrook, Odessa, TX 79762-5917	Telephone No. 505.391.3158
Facility Name EVGSAU Satellite # 5	Facility Type Oil and Gas
Surface Owner State of New Mexico	Mineral Owner State of New Mexico
Lease No B-1404-2	


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	27	17S	35E					Lea

Latitude **32.80367N** Longitude **-103.43906W**

NATURE OF RELEASE

Type of Release Oil & Produced Water	Volume of Release 152 bbl (7 oil, 145 water)	Volume Recovered (3 oil, 124 water)
Source of Release 6 inch fiberglass trunk line.	Date and Hour of Occurrence 05/22/2006 1145hrs	Date and Hour of Discovery 05/22/2006 1245hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Silvia Dickey NMOCD	
By Whom? Steve Wilson	Date and Hour 05/22/2006 1420hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The 6 inch fiberglass trunk line parted due to a bruise on the pipe. Damaged section of pipe was removed and replaced.		
Describe Area Affected and Cleanup Action Taken.* The spill site covered 100'X150' of dry black soil/caliche rock pasture. A quick response plan will be implemented with the top contaminated soil being removed and disposed. The spill site will then be sampled and delineated, and a remediation plan will be submitted to the NMOCD.		



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kenneth N. Andersen</i>	OIL CONSERVATION DIVISION	
Printed Name: Kenneth N. Andersen	Approved by District Supervisor:	
Title: HSER Lead	Approval Date:	Expiration Date:
E-mail Address: ken.n.andersen@conocophillips.com	Conditions of Approval:	
Date: 05/26/2006 Phone: 505.391.3158	Attached <input type="checkbox"/>	

• Attach Additional Sheets If Necessary
 RP# 981
 facility - PAC0620935644
 incident - PAC0620935762
 application - PAC0620935899
 ~60-70'

Please Follow Rule 116D
 Submit Plan.
 Thanks Paul Sheeley x113
 6-14-06