

1220 South St. Francis Dr., Santa Fe, NM 87501
 P.O. Box 24222, Santa Fe, NM 87501-2422
 1220 S. St. Francis Dr., Santa Fe, NM 87501
 1220 S. St. Francis Dr., Santa Fe, NM 87501

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
 1220 South St. Francis Dr.,
 Santa Fe, NM 87501

Parm Kaur
 Bureau Manager

Submit 2 Copies to appropriate
 District Office in accordance
 with Rule 14 no later
 than 12:00 noon

Release Notification and Corrective Action

OPERATOR

Name of Company
 Duke Energy Field Services
 Address
 1825 West Maryland Hobbs, New Mexico 88240
 Facility Name
 E-3Line
 Surface Owner
 State of New Mexico

Initial Report

Contact

Dale Rondon

Telephone No.

(505) 290-5707

Facility Type

Pipeline

Submit 2 Copies to appropriate
 District Office in accordance
 with Rule 14 no later
 than 12:00 noon

AUG 2003
 Received
 Hobbs
 OCD

Issue No.

125262728-2003

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the North/South Line	Feet from the East/West Line	County	Lat.	Long.
H	20	TQ05	R37E	None	None	Lincoln	N 38° 38' 31.22"	W 107° 18' 54.62"

GW = -25'

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Natural Gas and Natural Gas Liquids	Unknown	12 pds
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery

Internal corrosion to the "L" on a valve setting. Line internally has 200 psi at 14 psi and 2.184 GPM with 115°F.

Was Immediate Notice Given?

Yes No Not Required

Is YES, To Whom?

Larry Lujan, NMOCDB Hobbs

Not Required

By Who?

Line Work Done

Was a Watercourse Impacted? Yes No

Is YES, Volume Impacting the Watercourse.

If a Watercourse was Impacted, Describe Fully.

NA

Describe Cause of Problem and Remedial Action Taken. The release occurred due to internal corrosion to the "L" on a valve setting on a transportation line. The line was shut in, the leak origin excavated and the "L" repaired.

Describe Area Affected and Cleanup Actions Taken.

Soil contaminated above the NMOCB Remedial Guidelines will be disposed of at an approved facility or remediated on site. Remedial Goals: TPH = 100 mg/Kg, benzene = 10 mg/Kg, and DTEX = 50 mg/Kg.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to MCR 124-240408 and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCB marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCB acceptance of a C-141 report does not affect the operator's responsibility for compliance with any other federal, state, local laws and/or regulations.

OIL CONSERVATION DIVISION

Printed Name: John Ward
 Email Address: jward@nmocd.state.nm.us

Approved by District Supervisor

Title: Senior Environmental Specialist
 Date: 10/16/03 Phone: (505) 829-4207

Approval Date:

Expiration Date:

Attached

Conditions of Approval:

RPT# 1003

Facility - PPAC0622748304
 Incident - PPAC0622748582
 Application - PPAC0622748840

DATES SUBJECT
 10/16/03