

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company ConocoPhillips Company	Contact Kenneth N. Andersen
Address 4001 Penbrook, Odessa, TX 79762-5917	Telephone No. 505.391.3158
Facility Name Santa Fe # 135	Facility Type Oil and Gas

Surface Owner State of new Mexico	Mineral Owner State of New Mexico	Lease No NM-015221
--	--	---------------------------

LOCATION OF RELEASE API# 30025324380000

Unit Letter L	Section 31	Township 17S	Range 35E	Feet from the 1743	North/South Line S	Feet from the 808	East/West Line W	County Lea Co.
-------------------------	----------------------	------------------------	---------------------	------------------------------	------------------------------	-----------------------------	----------------------------	--------------------------

Latitude **32.789054N** Longitude **-103.50287W**

NATURE OF RELEASE

Type of Release Produced oil & water	Volume of Release 52 bbl (5 oil, 47 water)	Volume Recovered (3 oil, 37 water)
Source of Release Wellhead stuffing box packing	Date and Hour of Occurrence 09/05/2006 0230hrs	Date and Hour of Discovery 09/05/2006 1030hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton NMOCD	
By Whom? Ken Andersen	Date and Hour 09/06/2006 1715hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Stuffing box packing failure due to pumping unit misalignment. Realign pumping unit and repack stuffing box.

Describe Area Affected and Cleanup Action Taken.* **10800** **3600**

180'X60' of rain soaked caliche wellhead pad, 180'X60' of rain soaked black soil/caliche rock, & 60'X60' of rain soaked black soil/caliche rock pasture with no cows present. Picked up the free standing fluid which consisted mostly of rain water and scraped off the top layer of contaminated soil. The spill site will be delineated and remediated in accordance with NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kenneth N. Andersen</i>	OIL CONSERVATION DIVISION	
Printed Name: Kenneth N. Andersen	Approved by District Supervisor: <i>[Signature]</i>	
Title: HSER PSM Lead	Approval Date: 9.12.06	Expiration Date: 11.6.06
E-mail Address: ken.n.andersen@conocophillips.com	Conditions of Approval: SUBMIT DELINEATION SAMPLES & PLAN OF ACTION	Attached <input type="checkbox"/>
Date: 09/07/2006	Phone: 505.391.3158	

- Attach Additional Sheets If Necessary

incident - nPAC0625530179
application - pPAC0625530382

RP# 1030