


Sep. 12. 2006 3:23PM

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1351 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



For
Revised Octal

Submit 2 Copies to a
District Office in a
with Rule 1
si

Release Notification and Corrective Action

Name of Company <u>Apache Corp.</u>		Contact <u>Hub Perry</u>	
Address <u>17 Hess Lane</u>		Telephone No <u>(505) 441-6600</u>	
Facility Name <u>Selby Maveety #3</u>		Facility Type <u>Flowline Leak</u>	
Surface Owner <u>Darrell Borden</u>		Mineral Owner <u>State NM</u>	Lease No. _____

OPERATOR

☒ Initial Report☐ Final ReportLOCATION OF RELEASE API# 30025339440000

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<u>1K</u>	<u>35</u>	<u>19S</u>	<u>36E</u>	<u>2310</u>	<u>South</u>	<u>1650</u>	<u>West</u>	<u>Lea Co</u>

Latitude 48° 36.827 Longitude W 103° 19.871
80/20 60/10

NATURE OF RELEASE

Type of Release <u>Flowline Leak</u>	Volume of Release <u>100 BBL</u>	Volume Recovered <u>70 BBL</u>
Source of Release <u>Hole in Line</u>	Date and Hour of Occurrence _____	Date and Hour of Discovery _____
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>Pat Caperton</u>	
By Whom? <u>Hub Perry</u>	Date and Hour <u>9/12/06 3:00P</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.

Describe Cause of Problem and Remedial Action Taken.

Hole in Flowline releasing Fluid. Trucks called and All Fluid was Rec

Describe Area Affected and Cleanup Action Taken.

Approx 1200 ft - South West of Maveety. Fluid from Flowline spilled out. Vacuum trucks picked up all Fluid

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of his should their operations have failed to adequately investigate and remediate contamination that poses a threat to ground water, surface water, human or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any of federal, state, or local laws and/or regulations.

Signature: <u>Hub Perry</u>		OIL CONSERVATION DIVISION	
Printed Name: <u>Hub Perry</u>		Approved by District Supervisor:	
Title: <u>Super II</u>		Approval Date:	Expiration Date:
E-mail Address: <u>Hub.Perry@ksa.apachecorp.com</u>		Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>9/12/06</u>	Phone: <u>441-6600</u>		

Attach Additional Sheets If Necessary

Incident - NPAC0625645487
application - PPAC0625645749

RP# 1032

NEW MEXICO ONE CALL: 800-321-2537

394 - 21601

EPI CODE: 3897

ONE CALL INFORMATION

ISSUED:

COMPANY	APACHE	
COMPANY TELEPHONE		
COMPANY REPRESENTATIVE		
LEASE OR STATION NAME	Selby Maveety #1 FlowLine Row	
NEAREST COMMUNITY	Monument	
Driving Directions	From Int. St 322 in Monument, go West for 30, North for .4, NorthWest for .3, West for .7, NorthWest down Row for 150 Ft. Set 500' Rod flag	
LEGAL DESCRIPTION	S 1/4 Sec. 35 T19S R36E	
Reason for One Call	Excavating	
Contractor	ENVIRONMENTAL PLUS, INC. (EPI), EUNICE NEW MEXICO	
Contractor Number	441-4974	
Contractor Representative	George Blackburn	
CONFIRMATION NO.	2006- 38 0022	
Effective Period	9.13 9.27 - 9.25	
Company Contacted	Duke /	Southern Union
Company Contacted	Targa /	
Company Contacted	Sid Richardson	
Company Contacted	PNM	
Company Contacted	Rice /	
Company Contacted	EPFS	
Company Contacted	Centurion	
Company Contacted	Holly Pipeline /	
Company Contacted	Plains /	
Company Contacted	Apache	
Respot Confirmation #		
Respot Confirmation #		
Respot Confirmation #		
Latitude		
Longitude		
Land Owner		

Preliminary delineation will occur during soil removal with soil samples being collected from the floor and sides of excavation and analyzed for chloride in the field. Trenches down to a depth of 12-feet below ground surface will be excavated and sampled as indicated by the field data. Trenches will be strategically located in the pooling areas, longest residence times or excavated every 50-feet along the flowpath. If delineation cannot be achieved by trenching, a delineation work plan proposing deeper soil borings will be developed and submitted to the NMOCD for approval.

Please contact either Mr. Hub Perry at 441.6600 or myself at the office if there are any questions.

Pat McCasland
Environmental Plus, Inc.
PO Box 1558
2100 Avenue O
Eunice, New Mexico 88231
505.394.3481 (office)
505.390.7864 (mobile)
505.394.2601 (fax)

Johnson, Larry, EMNRD

From: Pat Mccasland [pmccasland@envplus.net] **Sent:** Tue 9/12/2006 5:56 PM
To: Johnson, Larry, EMNRD
Cc: Hub Perry (Apache); Mike Warren; Ken Marsh (CRI); Guinn Burks; 'Cody Miller'; Daniel Dominguez (EPI); Dave Duncan (EPI); 'Jason Stegemoller'; Jessica Harper (EPI); 'Roger Boone'
Subject: Apache Selby Maveety #3 Mitigation/Remediation and Preliminary Delineation
Attachments:

Mr. Johnson,

Environmental Plus, Inc. (EPI), on behalf of Apache Corporation and with knowledge of the landowner (Darrel Be Ken Marsh as representative (505.631.6979)), will be excavating and disposing of the upper 2-feet of soil impacted by the release in the Apache Corp. Selby Maveety #3 flowline. The soil will be disposed of in the Controlled Recovery (CRI) facility. The initial C-141 submitted previously and the New Mexico One Call information, with driving directions included below for your reference.