

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Chevron USA Inc.	Contact Wayne Minchew
Address HCR 60 Box 423 Lovington, NM 88260	Telephone No. 505-396-4414
Facility Name West Lovington Unit	Facility Type Well 24

Surface Owner State of NM	Mineral Owner State of NM	Lease No. B4286-1
---------------------------	---------------------------	-------------------

LOCATION OF RELEASE API # 30025038690000

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	4	17S	36E					Lea

52'

Latitude _____ Longitude _____

NATURE OF RELEASE



Type of Release Produced Water	Volume of Release 225bbbls	Volume Recovered 220bbbls
Source of Release Packing leak on pump	Date and Hour of Occurrence 2:00pm 7/6/06	Date and Hour of Discovery 2:00pm 7/6/06
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton	
By Whom? Larry Williams	Date and Hour 7:30 am 7-11-06	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
While digging out bradenhead on well, back hoe dropped some dirt on piping and broke off tubing valve on well head. Back hoe built a berm around well can contained the water on location.

Describe Area Affected and Cleanup Action Taken.*
All fluid stayed on location and was picked up by vacuum truck and enviro-vac .No other remediation will be done

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name Larry Williams	Approved by District Supervisor: 	
Title: HES Champion	Approval Date: 9.20.06	Expiration Date: -
E-mail Address: lcwl@chevron.com	Conditions of Approval: -	Attached <input type="checkbox"/> -
Date: 7/11/06	Phone: 505-394-1237	

* Attach Additional Sheets If Necessary

incident - n PAC0626351274
application - p PAC0626351400

AP# 1041