

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1600 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Site # 68

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Dynegy Midstream Services, L. P.	Contact: Dave Harris
Address: PO Box 1909 Eunice, NM 88231	Telephone No. (505) 631-7069
Facility Name: Eunice Gathering System	Facility Type
Surface Owner: DK Boyd	Mineral Owner
Lease No. Cameron Production	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	11	23S	37E					

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Produced oil and water	Volume of Release: 40 bbls	Volume Recovered: 40 bbls
Source of Release: Pipeline leak	Date and Hour of Occurrence: 11/12/04	Date and Hour of Discovery: 11/12/04
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken. * Producer dumped liquids in a Dynegy 10" low-pressure gas gathering line. Line leak due to internal corrosion. Vac Truck was called and removed free liquids. DMS excavated approximately 6" of saturated soil from the top prevent further leaching. Site will be remediated per OCD guidelines.		
Describe Area Affected and Cleanup Action Taken.* 50' by 100'. Free liquid was removed. Vertical extent will be investigated and a clean-up plan submitted to the district office for approval.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 		OIL CONSERVATION DIVISION
Printed Name: Cal Wingham		Approved by District Supervisor:
Title: ES&H Advisor	Approval Date:	Expiration Date:
E-mail Address: cwvnr@dynegy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/18/04	Phone: (432) 688-0542	

* Attach Additional Sheets If Necessary

69'

Dec 06 04 01:45p Dynegy Midstream Services 432 688 0552 P. 2

facility - PPAC0627131801
 incident - PPAC0627131985
 application - PPAC0627132132

RP# 1047

Fac name = Dynegy Eunice Gathering Site #68
 Company = Zarqa