

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Plains Pipeline, LP	Contact	Daniel Bryant
Address	P.O. Box 3119 - Midland, Tx 79702	Telephone No.	(432) 557-5865
Facility Name	South Mattix Lact	Facility Type	Crude Oil Gathering Pipeline
Surface Owner	Bill Grobe	Mineral Owner	
		Lease No.	

**LOCATION OF RELEASE**


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	15	24S	37E					Lea

65'

Latitude N 32° 32' 29.264" Longitude W 103° 15' 41.465"

**NATURE OF RELEASE**

Type of Release	Crude Oil	Volume of Release	10 bbls	Volume Recovered	0 bbls
Source of Release	2" Steel Pipeline	Date and Hour of Occurrence	10/07/2006 10:00	Date and Hour of Discovery	10/07/2006 11:00
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Gary Wink, NMOCD-Hobbs		
By Whom?	Daniel Bryant	Date and Hour	10/07/2006 14:50 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			



If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
External corrosion of a 2" steel pipeline caused the release. Pipeline was clamped to mitigate the release and will be replaced. Station has a daily throughput of 40.4 barrels. The pressure on the line is <50 lbs and the gravity is 38.4. Depth of the line at the release location is 6" bgs.

Describe Area Affected and Cleanup Action Taken.\*  
Affected soils will be remediated per applicable NMOCD regulatory standards.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Daniel Bryant</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Daniel Bryant	Approved by District Supervisor:	
Title: Environmental R/C Specialist	Approval Date:	Expiration Date:
E-mail Address: dmbryant@paalp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/12/06	Phone: (432) 557-5865	

\* Attach Additional Sheets If Necessary

Facility - SPAC0628633956  
Incident - NPAC0628634079

application - pPAC0628634516  
RP # 1078