

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Saber Resources LLC	Contact	Doug Keathley
Address	400 W Illinois, Ste 950	Telephone No.	432-685-0169
Facility Name	T D Pope 36-9	Facility Type	Producing Well

Surface Owner	Don Spears	Mineral Owner Fee		Lease No.	
---------------	------------	-------------------	--	-----------	--

**LOCATION OF RELEASE** *API # 30025052170000*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	36	14S	37E	660	North	1650	West	Lea

Latitude 37° Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Produced water/oil	Volume of Release	96	Volume Recovered	89
Source of Release	Flowline from Pope 36-9	Date and Hour of Occurrence	9/18/06 6 A.M.	Date and Hour of Discovery	9/18/06 8 A.M.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Gary Wink/Larry Johnson		
By Whom?	Doug Keathley	Date and Hour	9/18/06 3:00 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Connection on poly pipe flowline failed. Replaced 2" flowline with 3" flowline to reduce pressure in line.

Describe Area Affected and Cleanup Action Taken.\*  
Leak ran 180' down road and puddle in low spot in road. Spread out slightly on both sides of the road in low spot. Picked up water and oil and cleaned up area

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Doug Keathley</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Doug Keathley	Approved by District Supervisor: <i>Chris Williams</i>	
Title: VP of Production	Approval Date: <i>10/20/06</i>	Expiration Date:
E-mail Address: doug@saberresources.com	Conditions of Approval: <i>Sample &amp; find vertical &amp; horizontal extent of contamination</i>	Attached <input type="checkbox"/>
Date: 10/4/06	Phone: 432-685-0169	

\* Attach Additional Sheets If Necessary

*Incident - n PAC0629250671  
Application - pPAC0629250758*

*RP# 1101*